

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-00723

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
BP America Production Company

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

4. Well Location
Unit Letter M : 660 Feet From The S Line and 660 Feet From The W Line

Section 02 Township 18S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Workover ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6075' PBD: 60768 PERFS: 5958-5968' (old), 5770-5918' (new)

06.26.02: MIRUPU. NDWH. NUBOP. Rls pkr.

06.27.02: POH w/pkr. TIH w/bit & scraper. Test tbg to 5000# psi below slips. Tag @ 6068'. TOH.

06.28.02: Perf 2 JSPF, 236 holes 5770-5830', 5862-5918'. TIH w/pkr & plug.

07.01.02: Set RBG @ 5933'. PU 1 jt. drop SV. Pmp 500 gals 7.5% HCL to pickle tbg. Wait 30 mins. Swab back acid. Fish SV. Spot 70 gals 15% HCL. PU & set pkr @ 5842'. Pmp 2850 gals 15% HCL flush w/25 bbls 2% HCL wtr. Rls RBP. Move up & set RB @ 5842'. Spot 70 gals 15% HCL. PU & set pkr @ 5698'. Pmp 3050 gals 15% HCL flush w/25 bbls 2% KCL wtr. Used 175 ball sealers 1st stage, 200 ball sealers 2nd stage.

07.02.02: TOH w/pkr & plug. TIH w/tbg. NDBOP. NUWH. RTP. In 24 hrs pmp 0 bo, .1 bw, 118 mcf.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish

TITLE Sr. Administrative Assistant DATE 08.01.02

TYPE OR PRINT NAME Kellie D. Murrish

TELEPHONE NO. 505.394.1649

(This space for State Use)

Accepted for record - NMCCD

AUG 8 2002

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: