
Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department



District Office			u.	
DISTRICT I	OIL CONSERVA	= :	WELL API NO.	· · · · · · · · · · · · · · · · · · ·
P.O. Box 1980, Hobbs NM 88241-1980	2040 Pac		30-015-00730	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa re,	NM 87505	5. Indicate Type of Lease STATE [	X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. B-7244	
SUNDRY NO	TICES AND REPORTS OF	N WELLS		
	ROPOSALS TO DRILL OR TO DE ERVOIR. USE "APPLICATION FO -101) FOR SUCH PROPOSALS.)	OR PERMIT"	7. Lease Name or Unit Agreem Empire Abo Unit "L"	ent Name
I. Type of Well: OIL GAS WELL X WELL	OTHER			
2. Name of Operator / NRCO Permian			8. Well No. 14	
<ol> <li>Address of Operator</li> <li>Box 1089 Eunice, NM 8</li> </ol>	38231		9. Pool name or Wildcat Empire Abo	- <del> </del>
4. Well Location Unit Letter N : 660	Feet From The S	Line and	.980 Feet From The	W Line
Section 2	Township 18S	Range 27E	NMPM Eddy	County
	10. Elevation (Show	whether DF, RKB, RT, GR, 3539' GR	etc.)	
FREORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING C	asing [
EMPORARILY ABANDON  ULL OR ALTER CASING	PLUG AND ABANDON [ CHANGE PLANS [	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER:		ASING C
EMPORARILY ABANDON  ULL OR ALTER CASING  THER:  12. Describe Proposed or Completed Com	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER:	NG OPNS. PLUG AND A CEMENT JOB   ent dates, including estimated date	ABANDONMENT C
OTHER:  12. Describe Proposed or Completed Com	CHANGE PLANS  [Department of the content of the con	COMMENCE DRILL CASING TEST AND OTHER:	NG OPNS. PLUG AND A CEMENT JOB   ent dates, including estimated date	ABANDONMENT C
EMPORARILY ABANDON  FULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Comork) SEE RULE 1103.  Propose to TA wellbore Pkr or CIBP set @ 6017' Perforated interval 605 Load and test	CHANGE PLANS  Departions Clearly state all pertinons Clear	COMMENCE DRILL CASING TEST AND OTHER:  Lent details, and give pertine  Notify OCD 24 hrs	NG OPNS. PLUG AND A CEMENT JOB   ent dates, including estimated date	of starting any prop
EMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Complete Comple	CHANGE PLANS  Departions Clearly state all pertinons Clear	COMMENCE DRILL CASING TEST AND OTHER:  ent details, and give pertine Notify OCD 24 hrs	PLUG AND A CEMENT JOB  ent dates, including estimated date  prior to any work done	of starting any property of Starting and Starting
EMPORARILY ABANDON  ULL OR ALTER CASING  THER:  12. Describe Proposed or Completed Comork) SEE RULE 1103.  Propose to TA wellbore Pkr or CIBP set @ 6017' Perforated interval 605 Load and test	CHANGE PLANS  Departions Clearly state all pertine  0-6152  Lule 203  mencing operations  is true and complete to the best of my	COMMENCE DRILL CASING TEST AND OTHER:  Lent details, and give pertine  Notify OCD 24 hrs	PLUG AND A CEMENT JOB  Int dates, including estimated date  prior to any work done  ative Assistant DATE	ABANDONMENT Of starting any prop