

Mar 19 02 03:00

MORESCO

505-627-1299

P.2

Submit 3 Copies
to Appropriate
District OfficeState of New Mexico
Energy, Minerals and Natural Resources DepartmentForm C-100
Revised 1-1-99DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Aramis, NM 88210P.O. Box 2088
Santa Fe, New Mexico 87504-2088DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-00740	
1. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil & Gas Lease No. B6869	
7. Lease Name or Unit Agreement Name South Redlake Grayburg	
8. Well No. #40	
9. Pool name or Wellhead Red Lake Q-G-SA	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐ TNJ.	
2. Name of Operator McQuadrangle L.C.	
3. Address of Operator 7008 Salem Lubbock, TX 79424	
4. Well Location Unit Name: G 1650 Feet From The North Line and 2197 Feet From The East Line Section 2 Township 18S Range 27E NMPM Eddy County	
10. Elevation (Show whether DP, RKB, RT, CR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER: ☐
SUBSEQUENT REPORT OF:	
REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work); SEE RULE 1103.

145' Plug - Operator proposes to plug and abandon the above well as follows:

1. Spot 100' plug 1643-1543 and tag 1498-1643 TAG
2. Load hole with salt gel mud (10# brine with 25 # gel per barrel)
3. Spot 100' plug at 1600-1500 ft. and tag Part. CSG @ 150' (All strings) 150' Plug 0-150' inside & outside of All esp. strings
4. Spot surface plug at 60 ft. - surface
5. Cut off well head and set dry hole marker
6. Cut anchors and clean up location

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

TITLE

DATE

TYPE OR PRINT NAME: Donald G. Becker, Jr.

AGENT

TEL. 505-627-1290

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 4 2002

OR: ginally
Approved
3-22-02