

NO. OF COPIES RECEIVED	24
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

AUG - 7 1978

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ Fee ☐
5. State Oil & Gas Lease No.	B-9391

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator ESTATE OF FRED TURNER, JR. ✓	8. Farm or Lease Name STATE- H
3. Address of Operator P.O. Box 910, MIDLAND, TEXAS 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> <u>660</u> FEET FROM THE <u>EAST</u> LINE AND <u>1980</u> FEET FROM <u>NORTH</u> <u>2</u> <u>185</u> <u>27 E</u> THE <u>LINE</u> SECTION <u>2</u> TOWNSHIP <u>185</u> RANGE <u>27 E</u> NMPM.	10. Field and Pool, or Wildcat EMPIRE ABO
15. Elevation (Show whether DF, RT, GR, etc.) G.L. 3594	12. County EDDY

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>DEEPEN - RE-COMplete</u> ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>DEEPEN RE-COMplete</u> ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

MAY 23 1978 CACTUS DRUG. Co. MOVE IN & RIG UP OVER WELL
26 SQ PERF'S 5586-5602, 5624-42 IN 7" CSQ. WITH 150 SX CMT.
26 PERF. 7" @ 2500' sq 500SX TOP CMT. 1310' BEHIND 7"
27 PERF. 7"@ 1100' sq 500 SX CIRC. (10 3/4" CSQ 975)
29 SQ PERF'S 5756'-63' IN 7" WITH 150 SX CMT.
31 DRILL NEW 6 1/8" HOLE 5865-6140T.D. BOTTOM REACHED, 6-3-78
JUNE 3 1978 RUN & CMT. 510SX 4 1/2" CSQ CIRCULATED CMT. 6-4-78PBD 6100
5 PERF 4 1/2" 2 SHOTS/FOOT 5832-42, 5866-70, 5956-62
16 ACIDIZE ABOVE PERF'S 500 GAL. NEPE & SWAB TEST.
19 ACIDIZE ABOVE WITH 2500 GAL. PAD. ACID & SWAB TEST
22 ACIDIZE ABOVE WITH 5000 GAL. PAD. ACID & SWAB TEST
28 RELEASE PULLING UNIT. TEST WELL TO TANK BATTERY. TESTING
INTERMITTENTLY PRODUCED TO TEST WELL. INSTALL HEATER-TREATER TO HANDLE
WATER PRODUCTION. COMPLETE 8-2-78. WELL ON PRODUCTION 7-31-78. GOR TEST
8-4-78 24 HRS, 10/64 CK, 660# FTP, 28.29 BO + 8 BW, 292 MCF GAS, GOR
10,322. GOR FOR C116 TO BE TAKEN 8-7 TO 8-8-78.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chas. A. Lutz TITLE PROD. SUPT. DATE AUGUST 4, 1978

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE AUG - 8 1978

CONDITIONS OF APPROVAL, IF ANY: