

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions
verse side)

7*
2e-

Copy TO DH
Form approved.
Budget Bureau No. 42-21424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Atlantic Richfield Company		8. FARM OR LEASE NAME Mann B Federal	
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL & 990' FEL (Unit letter P)		10. FIELD AND POOL, OR WILDCAT Empire Yates 7Rivers	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 3-18S-27E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) Unknown		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

RECEIVED

APR 29 1977

O. C. C.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) Plug & Abandon <input checked="" type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 409'. Presently completed OH 352-409'.
7" 20# csg set @ 352' & cmtd w/25 sx.
Propose to plug & abandon in the following manner:
1. Dump Redi-mix cmt from bottom to top of csg @ surface.
2. Install regulation dry hole marker.
3. Clean & level location.

RECEIVED

OCT 07 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Dist. Drlg. Supv.

DATE 10/5/76

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

APPROVED
APR 21 1977
[Signature]