

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-29278

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Hondo Oil & Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 2208, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

2190' FNL & 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hondo Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Red Lake Qn., Grbg., SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA

Sec. 4-T18S-R27E

12. COUNTY OR PARISH

13. STATE

Eddy

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) cleaned out

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

11/20/89 Cleaned well out to 2292' (PBTD). Perforated 1744-2190' with 46 shots.

11/22/89 Acidized 1974-2190' with 3000 gal. 15% NEFE acid + 4000# rock salt. Swabbed well back.

11/28/89 Acidized 1465-1938' with 3000 gal. 20% HV acid + 3000# rock salt. Swabbed well back.

12/02/89 Perforated 1270-1461' with 30 shots.

12/03/89 Acidized 1270-1461' with 3000 gal. 15% NEFE acid + 64 ball sealers. Swabbed well back.

12/05/89 Ran in the hole with 72 jts. 2 3/8" tbg. with SN set @ 2212'. Hung on a 2" x 1 1/2" x 12' RWTC pump. Started well pumping.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Petroleum Engineer

DATE 12/12/89

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

\*See Instructions on Reverse Side