

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other instru-
verse side)LICATE*
38 OR re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-061783(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

RECEIVED

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

AUG 5 1968

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surfaceD. C. C.
ARTESIA, NEW MEXICO

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

WINDFOHR Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

EMPIRE Abo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

4-18-27 NMPM

12. COUNTY OR PARISH 13. STATE

EDDY N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GR, etc.)

3566' R.D.B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In an effort to reduce GOR propose
remedial work as follows:

Set retainer @ 5535'. Perforate @ 5529 w/ 4 JS.
Establish injection. Squeeze behind 4 1/2" casing
w/ 7524 neat + .3 gal D23/5x followed w/ 1024 neat.
WOC. Drill and cleanout to PBD-5635.
Evaluate and restore to production.

TD- 5666'

PAD - 5635'

4 1/2" CSA 5666'

PERFS: 5540-80, 5610-20

TEST - 6-15-68, FLW 129 BO x 0 BW 24 1/2. GOR 5527.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

7-31-68

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

044- USGS-ART
1- NSW
1- SUSP
1- RRL
1- WINDFOHR

APPROVED
AUG 2 - 1968
R. L. DILLON
ACTING DISTRICT SUPERINTENDENT

See Instructions on Reverse Side