

UNITED STATES

SUBMIT IN TRIPLICATE

Form approved.
Budget Bureau No. 42 B142

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

LC 026874 (e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Petroleum Corporation of Texas

3. ADDRESS OF OPERATOR

Box 911, Breckenridge, Texas 76024

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surfaceUnit K, 1650' from S. line, 2330' from the West line,
S5, T18S, R27E

MAY 10 1977

O. C. C.
ARTESIA, OFFICE

2970

First

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Eaton Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Red Lake Queen, Grayburg S.

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

5-18S-27E-NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3487'

12. COUNTY OR PARISH

Eddy

13. STATE

New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) — Shut-off old perf. 1851-1855' X

(NOTE: Report results of multiple completion on well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-8-76 - Set CIBP @ 1845' dump 1 sack cement on top.

" - Set retrievable bridge plug @ 1842'.

" - Perf. 1816' to 1820' - 8 holes.

" - Perf. 1827' to 1831' - 8 holes.

9-10-76- Acidized and swab test.

9-11-76- Perf. 1628,42,46,52,62,73,78,84,92,97,1701 - 11 holes

9-13-76- Set bridge plug @ 1725' set packer @ 1575'.

Acidized and swab test.

9-14-76- Swab test - Pulled bridge plug and packer - ran packer.

9-15-76- "Frac." well

9-16-76- Swab well.

9-17-76- Swab well.

9-18-76- Swab well.

9-20-76- Swab well.

9-21-76- Put well back on pump.

RECEIVED

MAY 09 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles J. Hubblefield

TITLE

Engineer

DATE May 5, 1977

(This space for Federal or State office use)

APPROVED BY

Joe D. Lara

TITLE

ACTING DISTRICT ENGINEER

DATE MAY 9 - 1977

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side