

EST
DP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	300150081
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name West Red Lake
2. Name of Operator Hondo Oil & Gas Company	8. Well No. 6
3. Address of Operator P. O. Box 2208, Roswell, NM 88202	9. Pool name or Wildcat Red Lake Qn-Grbg-SA
4. Well Location Unit Letter <u>K</u> : <u>2580</u> Feet From The <u>West</u> Line and <u>2460</u> Feet From The <u>South</u> Line Section <u>7</u> Township <u>18S</u> Range <u>27E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3294' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforated & Acidized Lwr. S. A. <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/23/92 POH w/ rods & pump.
2/24/92 Tagged PBTD @ 1714' & POH w/ tbg.
2/26/92 PU 3 7/8" bit, 4 - 3 1/8" DC's & TIH. Tagged fill @ 1721'. Cleaned out 5" csg to 1753' & drilled out CIBP. Cleaned out to 1770', circ hole clean & POH & LD DC's & bit.
2/27/92 Ran GR-CNL-CCL log from 1771'-800'. POH RIH w/ 3 1/8" csg gun & perf'd the S. A. "C" zone w/ 1 JSPF from 1740'-1754' for a total of 15 holes (.44" EHD). TIH w/ pkr to 1488' & acidized San Andres perms 1582'-1592', 1640'-1660', 1688'-1691', 1740'-1754' w/ 2500 gals of 15% NeFe w/ 1 gal/1000 corrosion inhibitor, 2 gal/1000 Ne surfactant, 1 gal/1000 EST surf & 5 gal/1000 citric acid, ISIP 900 psi.
2/29/92 TIH w/ 2" X 1 1/2" X 12" pump & rods. Started well pumping.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. L. Buttross Jr. TITLE Petroleum Engineer DATE 03/13/92
TYPE OR PRINT NAME E. L. Buttross, Jr. TELEPHONE NO. 625-6732

(This space for State Use)

ORIGINAL SIGNED BY
KURT WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE MAR 26 1992

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL TO WELL FILE. XC: Bruce, Ernie, Artesia, Exploration, Acctg, Karla