

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
 FEB 12 1970
 O. C. C.
 ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name West Red Lake Unit
8. Farm or Lease Name West Red Lake Unit
9. Well No. 11
10. Field and Pool, or Wildcat Red Lake-Grayburg S.A.
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Atlantic Richfield Company
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER <u>0</u> <u>1890</u> FEET FROM THE <u>East</u> LINE AND <u>990</u> FEET FROM THE <u>South</u> LINE, SECTION <u>7</u> TOWNSHIP <u>18-S</u> RANGE <u>27-E</u> NMPM.
15. Elevation (Show whether DF, RT, CR, etc.) 3292' Grd.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Convert to Water Injection	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In accordance w/NMOCC Order No. R-3469, we propose to convert the above well to dual water injection as follows:

1. Clean paraffin and scale from tubing and casing.
2. Perforate Grayburg 1038-47 w/2 JSPF and treat w/250 gallons 15% HCl acid and 10,000 gallons slick water containing 10,000# of 20/40 sand.
3. Set tension packer on 2" tubing at approximately 1080'.
4. Start water injection down tubing in San Andres perforations 1642-1737 and down 2-3/8" x 4-1/2" annulus into Grayburg perforations 1038-47.

Work will commence approximately 2/16/70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. D. Stitches TITLE Dist. Drlg. Supervisor DATE 2-10-70

APPROVED BY W. A. Gussert TITLE OIL AND GAS INSPECTOR DATE FEB 12 1970

CONDITIONS OF APPROVAL, IF ANY: