


(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 067858

Unit

DEC 18 1958



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
<u>Temporarily Abandoned</u> <input checked="" type="checkbox"/>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

USA MALCO REFERENCE "A"

December 1, 1958

Well No. 2 is located 1650 ft. from N line and 1980 ft. from W line of sec. 11

SE/4 NW/4 Section 11  
(1/4 Sec. and Sec. No.)

16 - S  
(Twp.)

27 - E  
(Range)

N.M.P.M.  
(Meridian)

El Aire Abn  
(Field)

Eddy  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 3589 ft. 108

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above well was drilled to a total depth of 6179' and encountering no commercial production the well has been temporarily abandoned as follows: Spotted 50 sacks plug from 6179' - 6037' and spotted 15 sacks plug from 1004' - 975' in bottom of 8-5/8" surface casing. Steel cap welded over surface casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Post Office Box 68

Hobbs, New Mexico

By Ralph Henderson

Title Field Superintendent