(Rovember 1983) (Formerly 9–331) DEPARTN T OF THE INTERIOR verse side) BUREAU OF LAND MANAGEMENT						5. LEASE DESIGNATION AND SERIAL NO. LC 067858		
(Do		NOTICES AND proposals to drill or to PPLICATION FOR PER		ON WELLS ack to a different reservoir. opossis.)	6. IF IND	IAN, ALLOTTEE OR TR	IBE NAME	
OIL WELL	GAS O1	rees /		RECEI		GREEMENT NAME		
2. NAME OF OPERATOR ARCO Oil and Gas Company 3. ADDRESS OF OPERATOR				SEP 28"	8. FARM OF Empire 9. WELL 1	8. FARM OR LEASE NAME Empire Abo Unit "M" 9. WBLL NO.		
P. Q. 4. LOCATION See also At surface	space 17 below.)	idland, Texas and in acc		O. C. Btate requirements. ARIESIA	Emp	AND POOL, OR WILDO DIRE Abo T., B., M., OR BLK. ANT VIEW OR AREA		
14. PERMIT N	10.	15. ELEVATIONS	(Show whether DF,	RT, GR. etc.)		TY OR PARISH 13. E	TATE	
30-01	5-00866		3547 GR		Edd	ly I	MV	
16.	Che	ck Appropriate Box	To Indicate N	ature of Notice, Report	, or Other Data	1		
	NOTICE OF	INTENTION TO:		s	UBSEQUENT REPORT	· OF:		
TEST WA	ATER SHUT-OFF	PULL OR ALTER C	!	WATER SHUT-OFF		REPAIRING WELL		
	R ACIDIZE	ABANDON®		FRACTURE TREATMENT SHOOTING OR ACIDIZIN	i !	ALTERING CASING ABANDONMENT®	-	
HEPAIR V	WELL	CHANGE PLANS	((Other) Recomp	lete same a	PAA	x	
(Other)	 .	· · · · · · · ·		Note: Report Completion or R details, and give pertinent	results of multiple ecompletion Report	completion on Well t and Log form.)	1	
7-29-87	Isolate hole Set CR at 60 Ran temp sur Perf Abo f/6 Swab test 10	6006-6012. Acc	21-6034. 100 sx. low behind 5 1z'd w/800 g	5-1/2 csg at ±140 gals.	00'.	Sep AR		
·	Perf Abo f/5970-5986. Acdz'd w/1000 gals. Swab test 100% water w/trace of oil & slight show of ga Set CIBP at 5920 & dumped 35' cmt on top. Perf 4 sqz holes at 1458 & estab circ to surf. Set CR at 1350. Sqz'd w/700 sx. Circ cmt to surf. Dump 100' cmt on top of CR. Spot cmt plug f/900-1000 & f/surf-110'.				gas.	16 10 50 AN 187	RECEIVED	
						Part II. 10-2-8 Part)-2 `>	
18. I hereby of SIGNED	certify that the foreg	uing is true and correct	913	5-688-5672 r. Tech. Spec.		9-14-87		
. <u> </u>	ce for Federal or Sta	ite office use)			ACCEPTE			
APPROVED BY						DATE		
Approvi Liau,ity suriace	et production of the restoration is some	១០/៦ គេប្រើ គ្រឹះក្នុង្គ	See Instructions	on Reverse Side	04 % 58&	SJS D, NEW MEX	MC:	