

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE	X	NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE	X	NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico

October 7, 1963

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the Humble Oil & Refining Co.
Abo Chalk Bluff Draw Unit Well No. 14 in F
 (Company or Operator) Lease (Unit)
SE 1/4 NW 1/4 of Sec. 16, T. 18-S, R. 27-E, NMPM., Empire Abo Pool
 (40-acre Subdivision)
Eddy County.

RECEIVED

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

OCT 8 1963

O. C. C.
ARTESIA, OFFICE

1. Pull rods, pump and tubing.
2. Set C.I. bridge plug on wire line at 5562 feet.
3. Run tubing with squeeze retainer, squeeze with 100 sacks cement.
4. If satisfactory, drill out and circulate hole clean to 5555'.
5. Reperforate with one jet shot at each of the following depths: 5461, 5482, 5501, 5506, 5516, 5519, 5524, 5529, 5537 and 5542.
6. Run tubing.
7. Acidize with 15,000 gallons acetic acid. Drop one ball after each 1,000 gals. until ball out. Release balls and flush with remainder of acid.
8. Swab test.
9. If not top allowable reopen lower zone (5582-5699).

Approved OCT 8 1963, 19.....
Except as follows:Approved
OIL CONSERVATION COMMISSIONBy W. A. GressettTitle OIL AND GAS INSPECTORHumble Oil & Refining Company
Company or OperatorBy [Signature]Position Agent
Send Communications regarding well to:Name Humble Oil & Refining Co.Address Box 2100, Hobbs, N. M.

/mcb

**OIL CONSERVATION COMMISSION
ARTESIA DISTRICT OFFICE**

No. Copies Received 3

	TO DIVISION	
SECTION	/	
DATA FILE	/	
PRODUCTION		
STATE LAND		
U. S. G. S.		
TRANSPORTER		
DATE	1 -	
DEPT OF MINES		