

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**

NEW MEXICO OIL CONSERVATION COMMISSION

OCT 20 1975

**O. C. C.**  
**ARTESIA, OFFICE**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B - 11083</b>	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name <b>Artesia State Unit</b>
2. Name of Operator <b>Anadarko Production Company</b>	8. Farm or Lease Name <b>Tract No. 7</b>
3. Address of Operator <b>P. O. Box 67, Loco Hills, New Mexico 88255</b>	9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>B</b> , <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>1650</b> FEET FROM THE <b>East</b> LINE, SECTION <b>23</b> TOWNSHIP <b>18S</b> RANGE <b>27E</b> NMPM.	10. Field and Pool, or Wildcat <b>Artesia</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3510'</b>	12. County <b>Eddy</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pumped 100 sx cement plug @ 1925'.
2. Shut in 17 hours; wait on cement; tagged top of plug @ 1850'.
3. Circulated hole with mud.
4. Pumped 70 sx cement plug @ 1850'.
5. Shut in 17 hours; wait on cement; tagged top of plug @ 1620'.
6. Spotted 35 sx cement plug from 1525' to 1425'.
7. Spotted 35 sx cement plug from 1000' to 900'.
8. Spotted 35 sx cement plug from 540' to 340'.
9. Pumped 10 sx cement plug @ surface.
10. Erected dry hole marker, closed pits and cleaned location On 7-31-75.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by  
**Jerry E. Buckles**

TITLE **Area Supervisor**

DATE **October 13, 1975**

APPROVED BY *Leon Bergstrom*  
CONDITIONS OF APPROVAL, IF ANY

TITLE **OIL AND GAS INSPECTOR**

DATE **OCT 22 1975**