

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN T
(Other instruc on re-
verse side)

NM-7713

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 054205

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Atlantic Richfield Company		DEC 5 1974		8. FARM OR LEASE NAME West Red Lake Unit	
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240		O. C. C.		9. WELL NO. 21	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FNL & 2310' FEL (Unit letter B)		ARTESIA, OFFICE		10. FIELD AND POOL, OR WILDCAT Red Lake Grayburg SA	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3400' DF		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 8-18S-27E	
				12. COUNTY OR PARISH Eddy	
				13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Shut in ☐REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was shut in and date shut in is unknown. The well was shut in because it was uneconomical to produce. The well is being held for possible secondary recovery expansion. The expansion of waterflood should occur during month of October, 1975.

RECEIVED
OCT 29 1974
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Prod. & Drlg. Supt.

DATE October 31, 1974

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

WELL MUST

DATE

UNLESS FURTHER APPROVED, WELL MUST
BE PUT TO BENEFICIAL USE OR PLUGGED BY
APRIL OCTOBER 1 - 1975

*See Instructions on Reverse Side