## STATE OF NEW MEXICO MERGY AND MINERALS DEPARTMENT

TIOT AND WINTER THE BY		.,,,,
we, or cories acceives	1	
DISTRIBUTION		
SANTA FE		
FILE		4
U.S.O.S.		
LAND OFFICE		
OPPRATOR	1.7	

## OIL CONSERVATION DIVISION

DISTRIBUTION P. O. BOX 2088	Form C-103 · Revised 10-1-78
SANTAFE SANECEVEDNEW MEXICO 87501	
TILE	5a. Indicate Type of Lease
U.S.O.S.	State X Fee
AUG 2 7 1982	5. State Oil & Gas Lease No.
OPERATOR V	2029
SUNDRY NOTICES AND REPORTS ON WELLS  THE PORTS OF THE PROPERTY OF PERMIT ARTESTS CONTROL BACK TO A DIFFERENT RESERVOIR.	
OIL GAB OTHER. Water Injection Well	7. Unit Agreement Name South Redlake Grayburg
Name of Operator	8. Farm or Lease Name
Tom R. Minihan	South Redlake Grayburg
Address of Operator	9. Well No.
P.O. Box 4364 Midland, Tex. 79704	33
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER C 280 FEET FROM THE NOTTH LINE AND 1650 FEET FROM	Redlake Grayburg
THE West_line, Section 2 TOWNSHIP_ 18 S RANGE 27 E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
15. Elevation (Show whether OF, NT, ON, etc.)	Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF INTENTION TO: SUBSEQUEN	r REPORT OF:
PLUG AND ABANDON REMEDIAL WORK TO REMEDIAL WORK COMMENCE DRILLING OPNS.  CHANGE PLANS CASING TEST AND CEMENT JOB  OTHER  OTHER  C. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	ALTERING CASING  PLUG AND ABANDONMENT

Remove present plug inside 4 1/2 casing. Clean out to T.D. 1630'. Sand frac present injection interval and pump test well. Commence Sept. 20, 1982.

1. MIRU service unit. Install BOP. Attempt to remove present plug inside 4 1/2 casing. If successful will clean out to T.D. Sand frac. Equip to pump. Pump test for 30 days. Submit necessary papers to reclassify well. If unable to remove plug will submit necessary forms to P & A well.

it. I hereby certify that the information above is true and complete to the best of my knowledge and belief. OATE AUG 3 6 1982