

1-22-81

Western-Yates

State # 41

L-3-18-28

10" e 374'
8 1/4" e 715'

Field inspection showed surface plug not in well.
Boards over hole. Well seems to be 100-200' deep w/
no fluid in hole.

2-26-81 Visited w/ Leon Standard w/ Depco
They will study the well &
re-enter to re-plug or produce

TD 320'
TD + good plug
up to 200' + tag
Tie on to left

L-3-18-28

wtr 270-274 - no salt logged

A 3-18-28


wtr sand 290-95

C-3-18-28

wtr sand 290-305

C-3-18-28

wtr sand 280-85, 486-88 ^{salt wtr}



R 28 E

