Form 3160-5 (November 1983) (1-)rmerly 9-331)	UNITED STATES DEPARTM T OF THE INTER BUREAU OF LAND MANAGEME	SUBMIT IN TRACATES ON TE (Other instruct on respectively) RIOR (Other instruct on respectively) RIOR (Other instruct on respectively) RIOR (Other instruct on respectively)	Budget Bureau No. 1004-0135 \\ Expires August 31, 1985 \\ 5. LEASE DESIGNATION AND SERIAL NO. 30 015 01836 \(\text{M} \) \(\text{M} \) \(\text{H} \)
	DRY NOTICES AND REPORTS form for proposals to drill or to deepen or plu Use "APPLICATION FOR PERMIT—" for such	g back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS GAS WELL WELL	OTHER WIW	DEC 6 11 22 AM '88	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		CARL	8. FARM OR LEASE NAME
DEKALB Energ 3. ADDRESS OF OPERATOR	y Company V	AREA AEL O GARTERS	Dunn B O 2 & ,
800 Central,	Odessa, Texas 79761		27
4. LOCATION OF WELL (R. See also space 17 belo At surface	eport location clearly and in accordance with a w.)	ny State requ itérient. VED	10. FIELD AND POOL, OR WILDCAT Artesia, Q, Gbr.
1980' FSL &	660' FEL, Sec. 12, T-18s, R-	DEC 15 '88	11. SBC., T., R., M., OR BLE. AND SURVEY OR AREA Sec 12, T-18s, R-28e
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.) O. C. D.	12. COUNTY OR PARISH 13. STATE
	3622 DF	artesia, office	Eddy New Mexico
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
N	OTICE OF INTENTION TO:	SUBSEQU	ENT REPORT OF:
TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON*	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	REPAIRING WELL ALTERING CASING ABANDONMENT*
REPAIR WELL	Penrose Perfs X		of multiple completion on Well
17. DESCRIBE PROPOSED OR	COMPLETED OPERATIONS (Clearly state all pertinuell is directionally drilled, give subsurface lo	ent details, and give pertinent dates,	tion Report and Log form.) including estimated date of starting any i depths for all markers and zones perti-
	y Company plans to sqz the P to perfs from 2613 to 2677'		2205' and resume
Set RBP @ ap and test csg	p. 2300' & sqz perfs from 21 ·	85' thru 2205' w/300 sx	s cmt, drill out
	.7# J-55 plasticoated tbg an rom 2613' to 2677'.	d pkr set @ approx 2560	' & resume injection
18. I hereby certify that	the foregoing is true and correct		
(2.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1	Nue R. L. Denney TITLE C	hief Production Clerk	DATE 12-5-88
(This space for Feder	og tim om tok a tim≟ Till till till till till till till till		DATE 12-13.85
CONDITIONS OF AP	PROVAL, IF ANY:	· · · · · · · · · · · · · · · · · · ·	DATE

Form 3160-5 (November 1983) (Cormerly 9-331) BUREAU OF LAND MANAGEMENT.	SUBMIT IN TRUICATES (Other instruct on reverse side) S. CONSISSION	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SPRIAL NO. 30-015-01836 NM-54184
SUNDRY NOTICES AND REPORTS ON (Do not use this form for proposals to drill or to deepen or plug back to Use "APPLICATION FOR PERMIT—" for such proposals		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS OTHER WIW	EC 6 11 22 AM '88	7. UNIT AGREEMENT NAME
	ARLA HEARS	B. FARM OR LEASE NAME Dunn B Old
3. ADDRESS OF OPERATOR 800 Central, Odessa, Texas 79761	RECEIVED	9. WBLL NO. 27
4. LOCATION OF WELL (Report location clearly and in accordance with any State See also space 17 below.) At surface 1980' FSL & 660' FEL, Sec. 12, T-18s, R-28e	DEC 15 '88	Artesia, Q, Gbr. 11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, C	O. C. D. ARTESIA, OFFICE	Sec 12, T-18s, R-28e 12. COUNTY OR PARISH 13. STATE
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, C	ik, etc.)	Eddy New Mexico
Check Appropriate Box To Indicate Natur	e of Notice, Report, or O	ther Data
NOTICE OF INTENTION TO:	SUBSEQU	ENT REPORT OF:
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Sqz Penrose Perfs X 17. Describe Proposed or Completed operations (Clearly state all pertinent det proposed work. If well is directionally drilled, give subsurface locations nent to this work.)* DEKALB Energy Company plans to sqz the Penros injection into perfs from 2613 to 2677' as for Set RBP @ app. 2300' & sqz perfs from 2185' to and test csg. Run 2 3/8" 4.7# J-55 plasticoated tbg and pkn thru perfs from 2613' to 2677'.	Completion or Recomple alls, and give pertinent dates, and measured and true vertical see perfs @ 2185 to ollows: thru 2205' w/300 sx	2205' and resume
18. I hereby certify that the foregoing is true and correct SIGNED R. L. Denney TITLE Chief (This space for Federal or State office use)	Production Clerk	12-5-88

*See Instructions on Reverse Side

TITLE _

APPROVED BY _______CONDITIONS OF APPROVAL, IF ANY:

DATE 12-13.88