

OIL CONSERVATION DIVISION

P. O. BOX 2088

Form 10-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.O.S.	
LAND OFFICE	
OPERATOR	☒

RECEIVED BY SANTA FE, NEW MEXICO 87501

JUN 11 1987

O. C. D.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-DRILL A WELL IN A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐

GAS WELL ☐

OTHER ☐

Name of Operator

W. E. Jeffers

Address of Operator

P. O. Box 65, Artesia, New Mexico 88211-0065

Location of Well

UNIT LETTER K, 1650 FEET FROM THE South LINE AND 1650 FEET FROM

THE West LINE, SECTION 15 TOWNSHIP 18S RANGE 28E NMPM.

15. Elevation (Show whether L.F., RT., GR., etc.)

5a. Indicate Type of Lease

State ☒

Fee ☐

5. State Oil & Gas Lease No.

B-11540

7. Unit Agreement Name

8. Farm or Lease Name

Vandeventer

9. Well No.

3

10. Field and Field, or Well at

Artesia - D-10-f

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Shot hole 2470' to T.D. 2500'. Well Only has 785' of 8 5/8" casing in hole - cemented w/50 sacks 8" open hole to 2383', 6 1/4" open hole to 2470' Propose to fill shot hole with mud and lost circulation material, spot 35 sax at 2400' and tag.

Spot 35 sax at Queen 1690' to 1790'.

Spot 35 sax 1225' to 1325'.

Spot 50' cement below and 50' above 8 5/8" casing shoe which is at 785' and tag.

Perforate 8 5/8" at 420' and spot 35 sax and tag.

Anticipate hole in casing at 130' - pump cement to top inside and out.

If no hole in casing, then set 10 sak plus in casing at top.

Set marker and clean up location.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

W. E. Jeffers

TITLE

Owner

DATE

June 10-87

Original Signed By
Mike Williams

APPROVED BY

Oil & Gas Inspector

TITLE

DATE

JUN 15 1987

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.C.C.C. in sufficient time to witness

Plugging