


NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION



Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
NM 647

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BOYD OPERATING COMPANY ✓	8. Farm or Lease Name Rotary State
3. Address of Operator P. O. Box 1756, Roswell, New Mexico 88201	9. Well No. # 4
4. Location of Well UNIT LETTER G 2100 N 1980 FEET FROM THE LINE AND FEET FROM THE E LINE, SECTION 20 TOWNSHIP 18S RANGE 28E NMPM.	10. Field and Pool, or Wildcat Art Qn Gbr SA
15. Elevation (Show whether DF, RT, GR, etc.) 3596 GR	12. County Eddy

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/13/83 Drove to location and rigged up. Unseated pump and pulled polish rod, 1-2', 1-4' and 1-10' X 5/8" subs, 94-5/8" rods, 2' sub and pump.

Made new pump up, 2' sub & rods in hole. Took 4' sub out. Ran sub and polish rod in hole. Seated pump. Replaced polish rod and waited for larger polish rod clamp. Spaced rods out and hung well on. Rigged down and cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don Boyd TITLE Operator DATE 8/18/83

APPROVED BY M. H. Williams TITLE OIL AND GAS INSPECTOR DATE AUG 26 1983

CONDITIONS OF APPROVAL, IF ANY: