CALMOT AND WARACTARD DECAMPTER			
NO. 01 LOPICS ALLEINED	OIL CONSERVA	TION DIVISON	
CISTRIBUTION	P. O. BOX 2088		Form C-103 * Revised 10-1-7
SANTA FE	SANTA FE, NEW	MEXICO 87501	Kerised is to
rice V			5a. inuicato Type ol 1 mise
U.1.G.3.			State X Foo
LAND OFFICE			5. State Oli 6 Gus Leage No.
CARAATOA		•	
			E-828
SUNDRY	NOTICES AND REPORTS ON	WELLS	
100 NET USE THIS FORM FUR PROPO USE "APPLICATION	SALS TO DRILL OR TO DELPER OR PLUG BA I FOR PERMIT - ** (FDRM C-1011 FOR SUCK	PACHER ALS.) BECEIVED	
		NECEIVED	7. Unit Agreement Name
	OTHER.		
curre of Coercitor		APR 0 8 1983	8. Furn or Lease Hume
• • • •			Gulf A
Yates Drilling (lompany	O. C. D.	9. hell No.
•			
207 S. 4th, Arte	sia, N.M. 88210	ARTESIA, OFFICE	#2
coation of well			10, Field and Pool, or Wildcat
Н	2310 rest room the North	LINE AND 990 FEET FROM	Artesia Qn. Grayburg SA
1			
West Past	19	RANGE 28E NMPM	\mathbf{A}
THE LINE, SECTION	TOWNSHIP	RANGE HAPM	.7/////////////////////////////////////
THURING WARDEN	15. Elevation (Show whether)	DF, RT, GR, etc.)	12. County
	3591 3589		Eddy
Manual Contraction of the Contra			
Check Ap	propriate Box To Indicate N	ature of Notice, Report or Ot	her Data
NOTICE OF INT	ENTION TO:	SUBSEQUEN	T REPORT OF:
LAFTEN BENTDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
· · · · · · · · · · · · · · · · · · ·	CHANGE PLANS	CASING TEST AND CEMENT JOB	L
LICERALTUR CASTNG		0TH6#	
	. []	VINSA	L
OTHER			

Cesartice Frenceses or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed warks SEE HOLE 1103.

Well was plugged back from 2434 T.D. to 2342 with gravel, 5 1/2" casing knocked off at 2006 ft. Mudded back from 2342 to 2020 and set 15 sax plug; mudded back to 510 ft. and set 10 sax plug, knocked off 8 5/8" casing at 320 ft. Set 10 sax plug at 320 ft., mudded to surface and set Regulation marker at top of hole in cement plug.

We propose to Re-enter; tie into old 8 5/8" with 8 5/8" casing at 320 ft. Cement with approximately 175 sacks. Clean out to 2006 ft., run 5 1/2" casing set over existing 5 1/2" with 7" sleeve. Cement with approximately 150 sacks. Clean out to T.D. - Log - Perforate - and Frac Metex zones.



. Thereby centify that the information above is true and complete to the beat of my knowledge and belief.

Janet Arice	me Production Clerk	ONTE 4-7-83
	Original Signed By Leslie A. Clements Supervisor District II	APR 1 1 1983

INDITIONS OF APPROVAL, IF ANY: