<b></b>		7		
NO. OF COPIES RECEI	IVED 3	_		Form C-103 Supersedes Old
DISTRIBUTION			RECEIVED	
SANTA FE		NEW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	/		6 1 1 10 7 A	
U.S.G.S.			C 1 4 1970	5a. Indicate Type of Lease
LAND OFFICE				State XK Fee
OPERATOR	7	1 [	<b>1. C.</b> S.	5. State Oil & Gas Lease No.
••••••••••••••••••••••••			SIA, DFFICE	647
	SUNDE	RY NOTICES AND REPORTS ON	WELLS	
(DO NOT USE T	HIS FORM FOR PR	RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEPEN OR PLUG E	ACK TO A DIFFERENT RESERVOIR.	
1.				7. Unit Agreement Name
OIL WELL	GAS WELL	OTHER. Injection well		
2. Name of Operator				8, Farm or Lease Name
AMEDICAN	DETDOFTMA	COMPANY OF TEXAS		Declary Weber Ober
3. Address of Operator		COMPANI OF TEARS		Resler Yates State
Por 1311	Dia Comin			
4. Location of Well	BIG SPLI	ng, Texas 79720		10, Field and Pool, or Wildcat
		200 The str		
UNIT LETTER		2390 FEET FROM THE West	LINE AND 2390 FEET P	Artesia
37			0.0-	
THE NOTEN	LINE, SECTI	ON TOWNSHIP 185	RANGE NN	арм. <u>()                                      </u>
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
VIIIIIIIIIIIIIII	////////	15. Elevation (Show whether		12. County
<u> </u>		<u> </u>	L	Eddy
10.	Check	Appropriate Box To Indicate N	ature of Notice, Report or	Other Data
N		NTENTION TO:		ENT REPORT OF:
PERFORM REMEDIAL WO	RK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	$\square$		COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	<u>}</u>	CHANGE PLANS	CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT XX
	<u> </u>			
OTHER			OTHER	
17. Describe Proposed work) SEE RULE	or Completed C	perations (Clearly state all pertinent deta	uils, and give pertinent dates, inclu	ding estimated date of starting any proposed
WORK) SEE ROLE	1103.			
10/27/70	Well was	backflowing too much to	spot bottom plug. Se	t cast iron bridge plug
	@ 1950.	Dumped 2 Sx cement on to	p of plug.	
		-		
11/11/70	Shot 4-1/	'2" csg @ 1481, 1418, 135	5 and 1293. Recovere	d 1293' 4-1/2" casing
	Shot 7" o	asing @ 1205 and 1138.		
		ng to 1300 (4-1/2" stub),	loaded hole with 50	Sx mud and 25 Sx cement
	Pulled th	og to 1120 (7" stub) and	spotted 25 sy coment	by mad and 25 by cement.
		1138' of 7" casing.	opoliced 25 5x cement.	
		ig to 400' and spotted 25	Cr comont of boos of	materia and
	Ran cubin	1/2" marker and 10 Sx ce	Sx cement at base or	water sand.
	incervais	between plugs filled wi	en mua.	
10/7/70	T			
12/7/70	Location	clean and ready for insp	ection.	
		·		
18. I hereby certify tha	t the information	above is true and complete to the best o	f my knowledge and belief.	
E 1	11		· · ·	
SIGNED ATT	XV.C. m	Denson TITLE AS	st. District Mgr. of	Prod. DATE 12/10/70
	······			
	12	e / As		
APPROVED BY	2 4	Jami Fine Ol	LAND GAS INSPECT <b>or</b>	JAN 14 1971
				······································

NO. OF COPIES RECEIVED	5		RECEIVEL	Form C-103
DISTRIBUTION				Supersedes Old
SANTA FE	1		NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	1		FED 4 1970	
U.S.G.S.	1			5a. Indicate Type of Lease
LAND OFFICE	1		<b>D.</b> C <i>.</i> C.	State 🗶 🛛 Fee
OPERATOR	1		ARTESIA, OFFICE	5. State Oil & Gas Lease No.
	4	JJ		647
(DO NOT USE THIS FO USE	SU APP	NDR)	( NOTICES AND REPORTS ON WELLS DISALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. DN FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	
1.				7. Unit Agreement Name
OIL GAS WELL WEL	ιL.	]	OTHER- Intertion	10 (Jr
2. Name of Operator				8. Farm or Lease Name
AMERICAN PERCO	FIN	CON	Grany of Texas	Resler Yates State
3. Address of Operator				9. Well No.
Box 1311, Big	ຣິກາ	ting.	Tezas 79720	31
4. Location of Well				10. Field and Pool, or Wildcat
UNIT LETTER		23	190 FEET FROM THE LINE AND 2390 FEET FROM	Arcasia
THE North	LINE,	SECTION	N TOWNSHIP RANGE 288 NMPM	
mmmm	$\overline{U}$	$\overline{\Pi}$	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
ΛΙΙΙΙΙΙΙΙΙΙΙΙΙ	11)		3569 GL	Eddy
16.	Ch	ack A	appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTI				T REPORT OF:
NOTI				
PERFORM REMEDIAL WORK			PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING			CHANGE PLANS CASING TEST AND CEMENT JOB	
			OTHER	
OTHER				
	ompl-	tail ()	erations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.		ieu Ope	erations (occur) state are perturber actuary, and geve perturbin autors electronic	,

- 1. Spot 50 sx cement plug on bottom (TB 2108) through 2" EUE tubing using sud laden fluid as displacing medium. 2. Cut off 4-1/2" casing at 1524' and spot 25 am cemant plug at 1520'.
- 3. Pull 4-1/2" casing.
- 4. Cut off 8-5/8" casing at 1500' and pull. 5. Spot 25 sx commut plug at 400' (base of water sand).
- 5. Flace 10 ax compat plug at surface and set 4-1/2" OD pipe merker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED JAC (Larra J. M. Denson TITLE A	sst. Dist. Mgr. of Producti	ODATE FODTUCIY	3, 1970
APPROVED BY W. a. Gresset TITLE	OIL AND GAS INSPECTOR	 Date	
CONDITIONS OF APPROVAL, IF ANY: Intervale between	- plugs filled with n	mul	