

W. E. Jeffers, Vandeyenter #1-D, 22-18-28

On 10/1/81, shot off and pulled 2101' of tbg, spotted 50 sx Class H @ 2100', tagged TOC @ 1930' (170' fill)

Attempted to pressure up on casing, could not pressure up.

On Oct. 2, 1981, tested casing and found hole between 186' & 248'.

Perf 4 holes @ 1550' and could not pump into formation @ 1000#.

Perf 4 holes @ 1450' could not pump into formation @ 1000#.

Spotted 30 sx @ 1575' calculated TOC @ 1425', perf 4 holes @ 1200' and squeezed with 50 sx Class H w/2% CC. Max. PP 400#, ISIP 400#

On 10/5/81, unable to pull packer from 1100', cut tbg @ 1000' and circulated hole with mud. Perf @ 685', set packer @ 1585' & squeezed with 35 sx cmt.

On 10/6/81, tagged TOC @ 535', perf 4 holes @ 450', pumped 35 sx cmt.

On 10-7-81, tagged TOC @ 380', pumped water thru hole in casing @ 185' and circulated fluid. Pumped 135 sx cmt. and circulated cmt.