Santa Fe, New Mexico

NOTICE OF INTENTION TO DRILL

Notice must be given to the Oil Conservation Commission or its proper agent and approval obtained before drilling begins. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in triplicate. One copy will be returned following approval. See additional instructions in Rules and Regulations of the Commission.

Artesia, New Mex	Leo November 30, 1949
OIL CONSERVATION COMMI Santa Fe, New Mexico,	
Gentlemen:	
You are hereby notifie	d that it is our intention to commence the drilling of a well to be known as
Burnham Oil Co. Vo	nieventer in NWLEWL
of Sec 22 , T_ 185	., R. 282, N. M., P. M., Artesia Field, Eddy County.
N	The well is 330 feet (1) (S.) of the line and 330 feet
	(E.) (#) of the line of Section 22, T. 18 S., R. 28 E.
0	(Give location from section or other legal subdivision lines. Cross out wrong directions.)
	If state land the oil and gas lease is No. B-11540 Assignment No.
	If patented land the owner is
	Address
	If government land the permittee is
	Address
	The lessee is Numble Cil & Refining Co.
AREA 640 ACRES	Address Kouston, Texas
LOCATE WELL CORRECTLY	We propose to drill well with drilling equipment as follows: Cable Tools

The status of a bond for this well in conformance with Rule 39 of the General Rules and Regulations of the Commission is as follows: Burnham O11 Company

We propose to use the following strings of casing and to land or cement them as indicated:

Size of Hole	Size of Casing	Weight Per Foot	New or Second Hand	Depth	Landed or Cemented	Sacks Coment
10	8	28	Sec. Hd.	400	Land	None
8	7	20	New	2000	Cement	50 Sx

DEC 8 1949	Sincerely yours,
except as follows:	Burnham Of L Company of Operator By E John July
OIL CONSERVATION COMMISSION,	Position Owner Send communications regarding well to
By Title ARTESIA KEPREELITATIVE	

ENERGY AND MINERALS DEPARTMENT		
	IL CONSERVATION EDEWEDO	fr. 1. 6 100
DISTRIBUTION	P. O. BOX 2088	Form C-103 Revised 10-1-78
BANTA FE	SANTA FE. NEW MEXICO 87501	
FILE UC	OCT 7 1982	5a. Indicate Type of Lease
U.S.O.S.		State X Fee
LAND OFFICE	O. C. D.	5. State Oli 6 Gas Lease No.
OPERATOR U	ARTESIA, OFFICE	B-11540
INA WAY USE THIS FORM FOR PROPOSALS TO	CES AND REPORTS ON WELLS	
L. OIL CAB CAB OTHER		7. Unit Agreement Name
2. Name of Operator	B. Farm or Lease Hame	
William E. Jeffers	Vandeventer	
13. Address of Operator	9. Well No.	
P. O. Box 65, Artesia, NM	1	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER D 330	Artesia	
THE West LINE, SECTION 22		
	12. County Eddy	
16. Check Appropri	iate Box To Indicate Nature of Notice, Report or C	Ither Data
NOTICE OF INTENTIC	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
	0THER	
OTHER	□	
		and the second

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Rig up to P & A, tubing stuck, unable to pump or work loose. Cut tubing off at 2101', spot 50 sax cement. Pulled on 7" casing - stuck at 300' to 400'. Run tubing back tag cement at 1884'. Perforate 7" casing at 1550', pressure up to 1000 1bs. thru packer set at 1488'. Perforate casing at 1450', set packer at 1395' pressure up to 1000 1bs. Run tubing open ended to 1581', spot 35 sax. Perforate casing at 1200' run packer and squeeze 50 sax, 20 in and 30 out. Packer stuck, fill hole with mud cut tubing. Perforate casing at 685' squeeze 35 sax, tag cement at 635'. Perforate casing at 450' run packer squeeze 35 sax, tag cement at 380'. Pump water down 7" casing, circulate to surface, squeeze 135 sax down casing, circulate to surface. Set monument.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.