STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

CITICIT MESS TAMPETURES DE	-1 -11	111416
MO. OF COPIES ACCEIVED		
NOITUEIRTZIO		
SANTA FE	17	
FILE	\prod	/
U.S.O.S.	Ι'	
LAND OFFICE	1	
OPERATOR	TT	1

OIL CONSERVATION DIVISION

HOLTERISTE	P. O. BO	KECELLER	Form C-103
	-{		Revised 10-1-78
BANTA FE	SANTA FE, NEW		
FILE	4	APR 28 1980	5a. Indicate Type of Lease
U.S.O.S.	4	-	State X For
LAND OFFICE	-	O. C. D.	5, State Oil & Gas Lease No.
OPERATOR !	J	O. C. S.	B11595
		ARTESIA, OFFICE	Arrer Tiller
IND MOY USE THIS FORM FOR PRO	RY NOTICES AND REPORTS ON PROSALS TO DRILL ON TO DEEPEN ON PLUG B	BACK TO A DIFFERENT RESERVOIR.	
1.			7. Unit Agreement Name
OIL X GAS WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
7 7 7 7	77- 1- 77		Gulf "B" State
Ray and Garel R. 3. Address of Operator	Westall		19. Well No.
3. Address of Operator			
P. 0. Box 4 Loc	o Hills. N. M. 88255		1
4. Location of Well			10. Field and Pool, or Wildcat
UMIT LETTER F	1980 FEET FROM THE N	LINE AND 1980 FEET FROM	Artesia Q-G
<u></u>			
W	on <u>23</u> township 18S	28E	
THE CINE, SECTION	on township	RANGENMFN	
THITTINITE.	15, Elevation (Show whether	DF, RT, GR, etc.)	12. County
	3507 GR.		Eddy
Check	Appropriate Box To Indicate N		
NOTICE OF IN	NTENTION TO:	SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL ON ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	-
POLE ON ACTEN CASING		OTHER	
OTHER Change Dump	-	O'NER	
OTHER CHANGE DOWN		•	
17 Describe Proposed or Completed Or	perations (Clearly state all pertinent det	ails, and give pertinent dates, includin	g estimated date of starting any proposed
work) SEE RULE 1103.			

Put electric motor on existing pump jack to start producing well.

3. I hereby certify that the information above is true and comple	ete to the best of my knowledge and belief.	
ENEO Kasen Westall	TITLE OO-OWNER	DATE 4-35-80
PROVED BY W. and Gussett	SUPERVISOR, DISTRICT II	DATE APR 29 1980
PROVED BY O COMPANY	71716	DATE 3 11 10 0 1000