

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

028 1979

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. M-19609
7. Unit Agreement Name
8. Farm or Lease Name STATE "24"
9. Well No. 1
10. Field and Pool, or Wildcat WILDCAT
12. County LEDDY

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER - BRINE WATER WELL
1. Name of Operator PERMIAN BRINE SALES & SERVICE, INC.		
2. Address of Operator P. O. Box 1591, Odessa, Texas 79760		
3. Location of Well UNIT LETTER M 1987.9 FEET FROM THE South LINE AND 1930.4 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 18 S RANGE 28 E N.M.P.M.		

15. Elevation (Show whether DF, RT, GR, etc.)

3503 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input checked="" type="checkbox"/>	Alter plugging program and complete.	<input checked="" type="checkbox"/>

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cleaned out surface plug. No Plug at 420-390. Cleaned out and bailed to 1540 feet. Hit cement plug. Called Bill Gressett and received approval to plug as follows:

35 sacks - 1540' - 1400'
50 sacks - 1000' - 740'

Dowell did cementing. Completed by hanging 2-7/8" tubing in open hole in salt section @ 660'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. L. Hickerson TITLE President DATE 12-27-78

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: