

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

RECEIVED BY
SEP - 2 1986

O. C. D.

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B 647

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ WELL GAS ☐ WELL OTHER: Injection	7. Unit Agreement Name
2. Name of Operator Kersey & Company	8. Farm or Lease Name Twin Lakes
3. Address of Operator P O Box 316, Artesia, NM 88210-0316	9. Well No. 8
4. Location of well UNIT LETTER L 2370 FEET FROM THE South LINE AND 270 FEET FROM THE West LINE, SECTION 28 TOWNSHIP 18S RANGE 28E NMPM.	10. Field and Pool, or Whicor Artesia Queen GBR SA
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Put cement plug 1380-1130'
Tag top plug 1380'
- Put cement plug 450-65'
Tag top plug 65'
- Put cement plug 60'-surface
- Install 4" pipe marker at surface

Post II 2
9-5-86
PFA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harold Kersey TITLE Operator DATE 8-29-86

APPROVED BY Danell Moore TITLE Geologist DATE 4/9/87

CONDITIONS OF APPROVAL, IF ANY: