

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
--	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well		7. Unit Agreement Name
2. Name of Operator American Petrofina Company of Texas		8. Farm or Lease Name Resler Yates State
3. Address of Operator Box 1311, Big Spring, Texas 79720		9. Well No. 384
4. Location of Well UNIT LETTER H 2310 FEET FROM THE North LINE AND 1300 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 18S RANGE 28E NMPM.		10. Field and Pool, or Wildcat Artesia
15. Elevation (Show whether DF, RT, GR, etc.) 3545 Gr.		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Start work by approximately 11-1-68

1. Pump 10 sack cement plug down 2 7/8" casing and spot over perforations from 2082-2086 using 10# mud as displacement medium.
2. Place 5 sack cement plug in top of 2 7/8" casing.
3. Set 4" pipe marker.

JCC/js

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. M. Denson</u>	TITLE <u>Asst. Dist. Mgr. of Production</u>	DATE <u>10-14-68</u>
APPROVED BY <u>W. A. Gussert</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>10-16-1968</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
OCT 15 1968
O. O. O.
ARTESIA OFFICE