## NEW MEXICO OIL CONSERVATION COMMISSION FEB 1 5 1960

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

ARTEDIA, CIFFICE

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

## Indicate Nature of Notice by Checking Below

Notice of Intention	NOTICE OF INTENTION TO	NOTICE OF INTENTION	
to Change Plans	TEMPORARILY ABANDON WELL	TO DRILL DEEPER	
Notice of Intention	Notice of Intention	Notice of Intention	
to Plug Well	to Plug Back	to Set Liner	
Notice of Intention	Notice of Intention	Notice of Intention	
to Squeeze	to Acidize	to Shoot (Nitro)	
Notice of Intention	NOTICE OF INTENTION	Notice of Intention	x
to Gun Perforate	(Other)	(Other)	

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

Breckenr	idge,	Texas
	(Place)	

February 11, 1960

Gentlemen:

Following is a Notice of Intention to do co	ertain work as described below at the		
Graridge Corporation	Transu Allon	Well No 5	٢
SE (Company or Operator) NE 1/4 SH 1/4 of Sec. 28	Lesse	Artesia	(Unit) Pool
(40-acre Subdivision)	······		

## FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Plan to move in spudder equipment, clean out and perform necessary

remedial work to re-complete well.

Approved..... Except as follows: FEB 1 5 1960 , 19.

Approved OIL CONSERVATION COMMISSION

By // I / SHIV/ 2 CY (2) THE ALL ARD GAS HOSPECTOR

Grapidge Corporation Smith arles W

Position Production Clerk Send Communications regarding well to:

Name Graridge Corporation

Address Box 752, Breckenridge, Texas

in the second	_		•
n generation and the second	RUNC	N	
		NO	
			<del></del>
NOTION OF CE			
MATE LAND CHRICE			ļ. 
0. S. C. S.			 
RANDOR R			
•		1	
COLAR OF MINES			

4

a to deare the state