		2										
	DISTRIBUTION											
SANTA F				NEW	MEXI	CO 01	IL CO	NSER	νατιον	COMMISSI	ON	FORM C-103 (Rev 3-55)
TRANSPORTER	011			M	ISCEL		EOUS	REP	ORTSO	N WELLS	\$	
PRORATION O			(5	ubmit te	o approp	oriate D	istrict	Office	as per Con	amission Ru	le 1106	}
	npany 16ge Co	rpoti	tion /		1. 22			ravel		tesia,		
Lease Toom	ey Alle	n /		Wel	11 No.	Unit L	Letter	Section	1 Township	88 -	Rang	;e 28 5.
Date Work P			Pool	<u>.</u>	esia	Y			County	Ed	dv	
<u></u>	<u></u>	J	тн			OF : (C	Check aj	ppropria	ate block)	<u></u>		
Beginni	ing Drilling O	peration			g Test an			[Explain):	REE	LIVED
🔲 Pluggin					dial Work							
Detailed acc	ount of work of	lone, na	ure and quan	tity of n	naterials	used, ai	ind resul	lts obta	ined.		DEC	2 0 1901
•• -) 9 29 -		b	ه. م. مو	\$	30.00	1 + -				n	. C. C.
11-2	2 3-61 C	edię	tool co	. 90 .	1 LOW	2038	• 10	207(SIA OFFICE
11-2	2 4-61 D:	rilli	ng line	broi	keL	ost 1	tool	\$.				
12_1	6-61 H	1.7 7 41	· Yatos		d in	his	rota	ry 6/	<u>uinmon</u>	t to fi	sh or	it tools.
		•							₩ <u>P</u> r 314 ₩44		**	
12-1	17-61 R	eco7(red all	to 0.	15.							
12-1												43 0.D.
12-1	9	•5# J	'-55 cas	ing 1	with .	Hall	iburt	ton i	float s	hoe and	3 64	mtralisers.
12-1	9 P:	•5# J	'- 5 5 cas et at 2	ing 1	with .	Hall	iburt	ton i	float s	hoe and	3 64	mtralisers.
12-1	9 P:	.5# J 1pe s	'- 5 5 cas et at 2	ing 1	with .	Hall	iburt	ton i	float s	hoe and	3 64	mtralisers.
12-1 Witnessed by	9 P: 0	.5# J 1pe s	'- 5 5 cas et at 2	ing 1 0981	vith and Position	Hall: cener	iburt nted	ton i viti	float s	hoe and	3 64	mtralisers.
Witnessed by	9 P: 0	.5# J ipe s ement	'-55 cas Not at 2 No.	1118 1 2098 1	vith and Position Supe	Hall: cener	iburi nted ender	ton i viti	float s h 100 s Company Grar	hoe and acks of idge Co	3 64	mtralisers. pozmix
Witnessed by	9 P: ¢	.5# J ipe s ement	'-55 cas Not at 2 No.	1118 1 2098 1	vith and Position Supe W FOR R	Hall: cener	ibur nted ender	ton i with mt DRK RE	float s h 100 s	hoe and acks of idge Co	3 64	mtralisers. pozmix
Witnessed by	9 P: ¢	.5# J ipe s ement	'-55 cas Not at 2 No.	1118 1 2098 1	vith and Position Supe W FOR R	Halls Cener Printe REMEDI	ibur nted ender	ton i with mt DRK RE	float s h 100 s Company Grar	hoe and acks of idge Co. NLY	3 66 1-1 rpors	mtralisers. pozmix
Witnessed by	9 P: • • • • • • •	• 5# J 1pe s •ment 1 1	'-55 cas Not at 2 No.	E LOW	vith and Position Supe FOR R ORIGI	Halls Cener Printe REMEDI INAL WE	ibur nted ender	ton i viti nt DRK RE	Company Grar EPORTS Of Producing	hoe and acks of idge Co. NLY	3 66 1-1 rpors	mtralisers. posmix ation ompletion Date
Witnessed by Paul D F Elev.	9 P: Darnel:	• 5# J 1pe s •ment 1 1	FILL IN	E LOW	vith and Position Supe FOR R ORIGI	Halls Cener Printe REMEDI INAL WE	and er	ton i viti nt DRK RE	Company Grar EPORTS Of Producing	hoe and acks of idge Co. NLY	3 64 1-1 rpors	mtralisers. posmix ation ompletion Date
Witnessed by Poul D F Elev. Tubing Diam Perforated In	9 P: Co Darnel: eter eter	• 5# J 1pe s •ment 1 1	FILL IN	E LOW	vith and Position Supe FOR R ORIGI	Halls Cener Printe REMEDI INAL WE D	1bur nted ender IAL WO ELL DA Dil String	ton s viti nt DRK RE ATA	Company Grar Grar PORTS ON Producing	hoe and acks of idge Co. NLY	3 64 1-1 rpors	mtralisers. posmix ation ompletion Date
Witnessed by Paul D F Elev. Tubing Diam	9 P: Co Darnel: eter eter	• 5# J 1pe s •ment 1 1	FILL IN	E LOW	vith and Position Supe FOR R ORIGI	Halls Cener Printe REMEDI INAL WE D	and er	ton s viti nt DRK RE ATA	Company Grar Grar PORTS ON Producing	hoe and acks of idge Co. NLY	3 64 1-1 rpors	mtralisers. posmix ation ompletion Date
Witnessed by Poul D F Elev. Tubing Diam Perforated In	9 P: Co Darnel: eter eter	• 5# J 1pe s •ment 1 1	FILL IN	BELOW	VI th and Position Supe V FOR R ORIGI PBTI	Halls Cener Printe REMEDI INAL WE D	1 bur nted ender IAL WO ELL DA Dil String	ton i viti nt DRK RE ATA g Diame	Company Grar Grar PORTS ON Producing	hoe and acks of idge Co. NLY	3 64 1-1 rpors	mtralisers. posmix ation ompletion Date
Witnessed by Poul D F Elev. Tubing Diam Perforated In	9 P: 0 Darnel: eter aterval(s) aterval Date o	. 5# d 1pe s ment	FILL IN	E LOW	VI th and Position Supe V FOR R ORIGI PBTI PBTI RESUL	Halls Cener Printe REMEDI INAL WI D Oi	1 bur nted end end IAL WO ELL DA Dil String Producing WORKC	ton i viti viti nt DRK RE ATA g Diame g Forma OVER Water P	Company Grar Grar PORTS Of Producing	boe and acks of idge Co. NLY ; Interval Oil Str	3 64 1-1 Fpore Co ting Dept	mtralisers. poznix ation ompletion Date th Gas Well Potential
Witnessed by Paul D F Elev. Tubing Diam Perforated In Open Hole In	9 P: 0 . Darnel: eter aterval(s) aterval	. 5# d 1pe s ment	-55 cas iet at 2 FILL IN Tubing Depth Oil Produc	E LOW	VI th and Position Supe V FOR R ORIGI PBTI PBTI RESUL	Halls Cener Printe Production Production	1 bur nted end end IAL WO ELL DA Dil String Producing WORKC	ton i viti viti nt DRK RE ATA g Diame g Forma OVER Water P	Company Grar Grar Producing etter Ation(s)	hoe and acks of idge Co. NLY ; Interval Oil Str	3 64 1-1 Fpore Co ting Dept	mtralisers. poznix ation ompletion Date
Witnessed by Part D F Elev. Tubing Diam Perforated In Open Hole In Test Before	9 P: 0 Darnel: eter aterval(s) aterval Date o	. 5# d 1pe s ment	-55 cas iet at 2 FILL IN Tubing Depth Oil Produc	E LOW	VI th and Position Supe V FOR R ORIGI PBTI PBTI RESUL	Halls Cener Printe Production Production	1 bur nted end end IAL WO ELL DA Dil String Producing WORKC	ton i viti viti nt DRK RE ATA g Diame g Forma OVER Water P	Company Grar Grar Producing etter Ation(s)	boe and acks of idge Co. NLY ; Interval Oil Str	3 64 1-1 Fpore Co ting Dept	mtralisers. poznix ation ompletion Date th Gas Well Potential
Witnessed by Paul D F Elev. Tubing Diam Perforated In Open Hole In Test Before Workover After	9 P: 0 Darnel: eter aterval(s) aterval Date o Test	• 5# d 1pe s • ment 1 T D f	-55 cas iet at 2 FILL IN Tubing Depth Oil Produc	E LOW	VI th and Position Supe V FOR R ORIGI PBTI PBTI RESUL	Halls Cener Printe REMEDI INAL WI D Oi Pr TS OF Production CFPD	1 bur nted and end IAL WO ELL DA Dil String Producing WORKO ion I hereb	ton i viti nt DRK RE ATA g Diame g Forma OVER Water P B	Company Grar Grar EPORTS Of Producing etter ation(s)	Acks of Acks o	3 G 1-1 Fpore Co ting Dept	mtralisers. poznix ation ompletion Date th Gas Well Potential
Witnessed by Paul D F Elev. Tubing Diam Perforated In Open Hole In Test Before Workover After	9 P: 0 Darnel: eter aterval(s) aterval Date o Test OIL CON	• 5# d 1pe s • ment 1 T D f	-55 cas iet at 2 FILL IN Tubing Depth Oil Produce B P D	E LOW	VI th and Position Supe V FOR R ORIGI PBTI PBTI RESUL	Halls Cener Printe REMEDI INAL WI D Oi Pr TS OF Production C F P D	1 bur nted and end IAL WO ELL DA Dil String Producing WORKO ion I hereb	ton i viti nt DRK RE ATA g Diame g Forma OVER Water P B	Company Grar Grar Producing Producing etter ation(s) Production PD	Acks of Acks o	3 General Stress	mtralisers. poznix ation ompletion Date th Gas Well Potential MCFPD
Witnessed by Part D F Elev. Tubing Diam Perforated In Open Hole In Test Before Workover After Workover	9 P: 0 Darnel: eter aterval(s) aterval Date o Test OIL CON	• 5# d 1pe s • ment 1 T D f	-55 cas iet at 2 FILL IN Tubing Depth Oil Produce B P D	E LOW	VI th and Position Supe V FOR R ORIGI PBTI PBTI RESUL	Halls Cened Printe REMEDI INAL WI D Oi Pr TS OF T Productio CFPD	1 bur nted nted nted inted	ton i vi ti vi ti nt DRK RE ATA g Diame g Forma OVER Water P B oy certif best of	Company Grar Grar EPORTS OF Producing etter Ation(s) Production BPD Fy that the in my knowled S. C. P.	Acks of Acks o	3 General Stress	mtralisers. poznix ation ompletion Date th Gas Well Potential MCFPD