

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-102  
Supersedes G-11  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
647

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Petroleum Corporation of Texas	Koyal Duke State
3. Address of Operator	9. Well No.
Drawer B, Artesia, New Mexico	1
4. Location of Well	10. Field and Pool, or Wildcat
0 2380' Footage not available 400' LINE AND 3500' FEET FROM	Artesia (H.S.)
SW 1/4, SW 1/4, NE 1/4 East 7'	
LINE, SECTION 29 TOWNSHIP 18S RANGE 28E N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Eddy

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pumped 25 sacks cement and rubber plug to TD 2040' with 10# mud. Top of plug at 1750'. Let set 48 hours and tested plug. Held OK. Cut 4 1/2" casing and 7" casing off at 440' (top of cement) and pulled same. Left 1600' of 4 1/2" casing, 1491' of 7" casing, and 933' of 10 3/4" casing in hole. Ran 2" tubing and loaded hole with 10# mud. Spotted 30 sacks cement from 390' to 450' and 5 sacks at surface with 4 1/2" marker set in top of surface. Pits have been filled and location levelled and cleared of junk.

RECEIVED

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Thomas A. Grissett TITLE Dist. Superintendent DATE 3-1-66

APPROVED BY W.A. Grissett TITLE Regional Supervisor DATE MAY 22 1966

CONDITIONS OF APPROVAL, IF ANY: