

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

**RECEIVED**  
 NEW MEXICO OIL CONSERVATION COMMISSION  
 MAY 10 1978  
**O. C. C.**  
 ARTESIA, OFFICE

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Yates Drilling Company ✓ 3. Address of Operator 207 So. 4th, Artesia, NM 88210 4. Location of Well UNIT LETTER <u>C</u> <u>380</u> FEET FROM THE <u>North</u> LINE AND <u>2110</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18S</u> RANGE <u>28E</u> NMPM.	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No. 7. Unit Agreement Name Artesia Metex Unit 8. Farm or Lease Name 9. Well No. 1 32 10. Field and Pool, or Wildcat Artesia
15. Elevation (Show whether DF, RT, GR, etc.) 3565 GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to squeeze Loco Hills zone for better distribution of water from (1864-1868), 1873-1878). Set Halliburton plug on tubing at 1900. Set Halliburton packer at 1800, squeeze with 100 sks Class C 4% gel - 3# salt thru 2-3/8 tubing. Set overnight. Pull packer - drill out cement and plug. Back on injection

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Morris TITLE Drilling Supervisor DATE 3/9/78  
 APPROVED BY R. C. Gressett TITLE SUPERVISOR, DISTRICT II DATE MAY 11 1978  
 CONDITIONS OF APPROVAL, IF ANY: