


NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.B.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

SANTA FE, NEW MEXICO 87501



1. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. State Oil & Gas Lease No.
647

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW	7. Unit Agreement Name
2. Name of Operator DEPCO, INC. ✓	8. Farm or Lease Name State 647 AC 711
3. Address of Operator 800 Central, Odessa, Texas 79761	9. Well No. 85
4. Location of Well UNIT LETTER G 1650 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 18s RANGE 28e NMPM.	10. Field and Pool, or Wildcat Artesia, Q, Grb, SA
15. Elevation (Show whether DF, RT, GR, etc.) 3537 DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-19-85: Ran cmt. bond log & found TOC @ 770'.

8-20-85: Spotted cmt plug from 2848' to 2505'. Spotted cmt. plug from 1646' to 1546'.
Perf @ 510' & set retainer @ 455' & pmpd 55 sxs cmt. thru perfs w/45' cmt.
on top of ret. Perf @ 325' & set ret. @ 272' & pmpd 55 sxs cmt. thru perfs
w/150 sxs cmt. on top of ret. to sfs. 9.5# mud pmpd between all plugs.

8-26-85: Set dry hole marker.

Post ID-2
9-26-85
P.A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Denney R. L. Denney TITLE Chief Production Clerk DATE 9-11-85
APPROVED BY Danell Moore TITLE Geologist DATE 12/4/85
CONDITIONS OF APPROVAL, IF ANY: