

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
--	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator American Petrofina Company of Texas		8. Farm or Lease Name Levera State
3. Address of Operator Box 1311, Big Spring, Texas 79720		9. Well No. 11
4. Location of Well UNIT LETTER I , 1578 FEET FROM THE South LINE AND 235 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 18S RANGE 28E NMPM.		10. Field and Pool, or Wildcat Artesia
15. Elevation (Show whether DF, RT, GR, etc.) 3650 Gr.		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-20-68 Ran 2" EUE tubing to 2150' and circulated hole with 10# mud.
Picked up tubing to 2025' and spotted 50 sack cement plug.
Pulled tubing up to 1500' and spotted 25 sack cement plug.

9-7-68 Shot off 8 5/8" casing at 580'. Pulled 1 joint and spotted 50 sack cement plug at 557' (Bottom of 10"). Pulled 174' of 10" casing, spotted 25 sack cement plug at 150'. Set 5 sack cement plug at surface and placed pipe marker.

RECEIVED

OCT 11 1968

O. C. C.
ARTESIA, OFFICE

JCC/js

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. M. Denson TITLE Asst. Dist. Mgr. of Production DATE October 10, 1968

APPROVED BY R. L. Denson TITLE SEALING OFFICIAL DATE 10/10/68

CONDITIONS OF APPROVAL, IF ANY: