Submit 3 Copies to Appropriate District Office

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT I

State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 Pacheco St.

clsf Form C-103 Revised 1-1-89

WELL API NO

30-015-02606 Santa Fe, NM 87505 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE X FEE 🗆 DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Empire Abo Unit "I" 1. Type of Well: GAS WELL WELL X OTHER 8. Well No. 2. Name of Operator 26 ARCO Permian 9. Pool name or Wildcat 3. Address of Operator Empire Abo P.O. Box 1089 Eunice, NM 88231 4. Well Location 185 Feet From The Line Line and Feet From The Unit Letter 1941.06 330 NMPM Range Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3678° DF Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: **NOTICE OF INTENTION TO:** ALTERING CASING REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. **CHANGE PLANS** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: -OTHER: -12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

		53/A	
I hereby certify that the information above is true and complete to the best of my ki	nowledge and belief.		
SEGNATURE BULLE H. Thursel	TITLE Administrative Assistant	DATE	06/07/99
SIGNATURE //			
TYPE OR PRINT NAME Kellie D. Murrish		TELEPHONE NO.	505-394-1649
(This space for State Use)			
(This space for State Use) Jim W. Bum Bloom	District Sepenie	w	
Blo	TITLE	DATE	10.99
APPROVED BY			
•			

TD: 6254' PBD: 6218' CR: 6045' PERFS: 5966-6000'

02/25/98: Set CR @ 6045'. Squeeze old perfs 6060-6096' w/75 sxs Class "C"

Neat. 2000#. Perf abo interval 5966-6000' w/1-11/16" strip guns, 68 holes. Acidize w/1000 gals 15% NEFE acid w/1000 gals condensate. Ran

75 ball searlers. RIH w-2/38" tbg. Set @ 2906'. SN @ 5929'.