

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

C.L. CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.O.S.	
LAND OFFICE	
OPERATOR	1

AUG 9 1979

O. C. C.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Simpson
9. Well No. 1
10. Field and Pool, or Wildcat Artesia Queen Grayburg, S.A.
12. County Eddy

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator W. C. Welch ✓
3. Address of Operator Rt. 1 Box 74 A, Artesia, N. M. 88210
4. Location of Well UNIT LETTER N, 330 FEET FROM THE S LINE AND 1650 FEET FROM THE W LINE, SECTION 7 TOWNSHIP 18 RANGE 28 NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cleaned out to 1900 + PB to 1700 w/ 65 sat.
This hole has been plugged back from T.D. to 1700 ft. It produced from the Queen (1660'-1700'). I intend to pull the rods and place a cement plug from 1700 ft. to 1600 ft., then fill the hole with mud and place cement in the top 10 ft. with a standard marker.

* 35 sat 1600-1700 + tag
35 sat. 350-450 + tag
15 sat at surface w/ marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. C. Welch TITLE Owner-Operator DATE 8/9/79

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE AUG 16 1979

CONDITIONS OF APPROVAL, IF ANY:

* as noted above

Notify N.M.O.C.C. in sufficient time to witness

Plugging