STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

(4-(c) -((()v))	3		
DISTRIBUTION			
SANTA PE	7		
FILE	1	_	
U.S.G.S.	1		
LAND OFFICE		[
OPERATOR	17		

UIL CONSERVATION DIVISION

PILE U.S.O.S. LAND OFFICE OPERATOR			P. O. BOX 2088		Form C-103 Revised 10-1
LAND OFFICE		•	ANTA FE, NEW MEXICO 87	501	
					State X Fee
OFERATOR					5, State Oil & Gus Lease No.
					OG-1644
	CHNDDV	L. VILCE C. A	NO DEPORTS ON WEIGHT		
(DO NOT USE THIS F	TAUNUK T DAGAR ARDA MAD DAGARAN J	THUTTUES A	ND REPORTS ON WELDES EIVED	RESERVOIR.	
		<u> </u>	to the second se		7, Unit Agreement Name
WELL X WELL		CTHE#+	JUL 2 7 198	2	Unit West Artesia Grauburd
ame of Operator					8. Farm or Lease Name Tr. 9
Marbob Energy	Corpora	tion 🗸	O. C. D.		West Artesia Grbg. Ut
ddress of Operator		=======================================	ARTESIA, OFFICE	.	9. Well No.
P.O. Drawer 2	17, Arte	sia, N.M.	88210	•	1
ocation of Well			The state of the s		10. Field and Foot, or Wildcat
C		990	North LINE AND 2	2310	Artesia Qn Grbg SA
			LINE AND	, ter prom	
West	LINE SECTION	8	TOWNSHIP 185 HANGE 2	?8E	
	rine, recitor		HANGE	NKIPM.	
		15, EI	evation (Show whether DF, RT, GR, etc.)		12. County
			3600' GR		Eddy ()))
	Check At	opropriate F	ox To Indicate Nature of Notic	e Report of Oth	er Data
NOTI		FENTION TO			REPORT OF:
	02 01 111		·	SOUSEQUENT	REPORT OF.
DAM REMEDIAL HORE	\overline{x}	ſ	PLUG AND ABANDON REMEDIAL WORK		ALTERING CATING
PORARILY ABAHDON	Ä		COMMENCE DRILL		
OR ALTER CASING	=	,	HANGE PLANS CASING TEST AND	يسحم	PLUG AND ABANDONMENT
		`	- 	CEMENT JOB	
THER					
We propose to 2 3/8" plastic	pull pac c coated	cker and t tubing an	ubing, clean out to TD of d <u>put back on injection.</u>	⁻ 2297', run n	ew packer, * Tost Csq te. 5
We propose to 2 3/8" plastic	pull pac c coated	cker and t tubing an	ubing, clean out to TD of d <u>pùt back on injection.</u>	⁻ 2297', run n	ew packer, * Tost (sq te. s
We propose to 2 3/8" plastic	pull pac c coated	cker and t tubing an	ubing, clean out to TD of d put back on injection.	- 2297', run n	ew packer, * Tosst Csoq te. 5
We propose to 2 3/8" plastic	pull pac	cker and t tubing an	ubing, clean out to TD of d put back on injection.	⁻ 2297', run n	ew packer, * Tost Cog to s
We propose to 2 3/8" plastic	pull pace coated	tubing an	ubing, clean out to TD of d put back on injection.		ew packer, * Toss (seg to s
2 3/8" plastic	pull pace coated	tubing an	a put back on injection.		ew packer, * Tool (e.g. (e. s.
2 3/8" plastic	pull pace coated	tubing an	a put back on injection.	d betsef.	ew packer, * Tost Cog to 5