

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL APINO.

30-015-03232

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-5084-76

7. Lease Name or Unit Agreement Name:

WLHU 25-1

7. Well No.

1

8. Pool name or Wildcat

Loco Hills Queen Grayburg,
San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☒ Injection

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter K : 2310 feet from the S line and 2310 feet from the W line

Section 1 Township T18S Range R29E NMPM County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

YATES PETROLEUM CORPORATION RESPECTFULLY PROPOSES TO PLUG & ABANDON AS FOLLOWS:
NOTIFY NMOCD 24 HOURS BEFORE STARTING PLUGGING OPERATIONS - 505-7481283

1. MIRU WSU & safety equipment. No casing recovery will be attempted.

2. RU WL: TIH w/ WL, set 7" CIBP @ 2566' - TOH. TIH w/ tubing, tag CIBP, load hole w/ plugging mud. Keep wellbore loaded w/ mud. Spot 35' sk Class C cement plug on top of CIBP.

3. TOH w/ tubing. MIRU WL to perf 7" casing w/ casing guns 4 shots @ 1090' & 535'.

4. TIH w/ WL, set cement retainer @ 990', TOH. TIH w/ tubing, load w/ plugging mud, sting into retainer & establish injection rate. Squeeze w/ 45 sx Class C cement, leave 35' of cement on top of retainer. TOH w/ tubing.

5. ND BOP'S; TIH w/ WL. Set cement retainer @ 435', TOH. TIH w/ tubing, load hole w/ plugging mud. Sting into retainer & establish circ.. Squeeze w/ 100 sx Class C cement w/ 5#/sx salt fr 535' to near surface. Leave 35' of cement on top of retainer; TOH w/ tubing.

6. Spot ~~15~~ Class C cement plug @ surface. Remove all equipment & install regulation marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Clack TITLE Regulatory Compliance Tech DATE 6-20-02

Type or print name Donna Clack

Telephone No. 505-748-1471

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any: