

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-015-03251

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-06058

7. Lease Name or Unit Agreement Name:

WLHU G4S Unit Tract 32C

Well No.

5

9. Pool name or Wildcat

Loco Hills-Q-GB-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐ Plug & Abandon ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter D : 990 feet from the North line and 990 feet from the West line

Section 2 Township 18S Range 29E NMPM County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11-15-2002 - Moved in and rigged up pulling unit and plugging equipment. Nippled down wellhead and nipped up BOP. Rigged up floor and tubing equipment. Rigged up wireline. RIH with CIBP and set CIBP at 2484'. While pulling out of hole, setting tool hung up and lost in well. Rigged down wireline. Moved in workstring. Shut well in for night.
11-16-18-2002 - RIH with 3-1/8" overshot and latched onto setting tool. POOH with over-shot and setting tool. RIH open ended to 2484'. Circulated hole with plugging mud. Spotted 30 sacks Class C Neat cement from 2484-2305'. POOH. Rigged up wireline. RIH and perforated 7" casing at 1075'. POOH and rigged down wireline. RIH with packer and tubing to 763' and set packer. Pressured up to 1500 psi. POOH with packer. RIH open ended to 1127'. Spotted 35 sacks Class C Neat cement. POOH. Shut well in for night. WOC.

11-19-2002 - RIH with tubing and tagged cement at 953'. POOH. Rigged up wireline. RIH and perforated casing at 560'. POOH and rigged down wireline. RIH with packer and tubing to 254' and set packer. Squeezed with 100 sacks Class C Neat cement from 560-460'. WOC 4 hours. POOH with packer. Rigged up wireline. RIH - did not tag cement. POOH and rigged

I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE.

SIGNATURE Donna Clark TITLE Regulatory Compliance DATE 11-26-02

Type or print name DONNA I. CLACK

Telephone No. 505-748-147

(This space for State use)

APPROVED BY

TITLE

JAN 15 2003