NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE /	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE /		2.1001110 11-03
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee.
OPERATOR /		5. State Oil & Gas Lease No.
SUNDRY	NOTICES AND DEPORTS ON WELLS	B-7072
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1.		7. Unit Agreement Name
	OTHER- WIW	West Loco Hills Unit
2. Name of Operator		8. Farm or Lease Name
Newmont Oll Company 3. Address of Operator		Tract 41
Room 303 First National Bank Building, Artesia, New Mexico		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER L 231	101 FEET FROM THE South LINE AND 330 FEE	T FROM LOCO HIIIS
THE West LINE, SECTION_	2 TOWNSHIP 185 RANGE 29E	_NMPM. (()))))))))))))))))))))))))))))))))))
	15. Elevation (Show whether DF, RT, GR, etc.)	12, County
		Eddy
16. Check App	propriate Box To Indicate Nature of Notice, Report	or Other Data
NOTICE OF INTE		QUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
7	CHANGE PLANS CASING TEST AND CEMENT JOB	·
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	f
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER CONVERT TO WIW	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER CONVERT TO WIW 17. Describe Proposed or Completed Operat work) SEE RULE 1103.	CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	PLUG AND ABANDONMENT