

COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUL 21 1983

O.C.D.

ARTESIA OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>WIW - TA P+R</u>	7. Unit Agreement Name <u>W.L.H.U. Grb #4 SD U</u>
2. Name of Operator <u>Newmont Oil Company</u> ✓	8. Farm or Lease Name <u>Tract 41</u>
3. Address of Operator <u>P. O. Box 1305 Artesia, N.M.</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>L</u> <u>2310'</u> FEET FROM THE <u>FSL</u> LINE AND <u>330'</u> FEET FROM THE <u>FWL</u> LINE, SECTION <u>2</u> TOWNSHIP <u>18</u> RANGE <u>29</u> NMPM.	10. Field and Pool, or Wildcat <u>Loco Hills (O.G.S.A.)</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3521'</u>	12. County <u>Eddy</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/18/83....Ran tbg to 2650' and spotted 100 sks cmt.

4/19/83....Perf base salt at 975'. Spotted 50 sks cmt at 975'. WOC. Tagged plug at 750'. Perf top salt at 420'. Spotted 50 sks cmt. WOC. Tagged at 425'. Re-squeezed w/50 sks cmt. WOC. Tagged at 340'. Set 15 sacks at surface and dry hole marker.

Location ready for inspection

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Area Manager.</u>	DATE <u>7/20/83</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>Geologist</u>	DATE <u>10/7/83</u>
CONDITIONS OF APPROVAL, IF ANY:		

Post ID-2
7-29-83
P+R