

RECEIVED BY

MAR 20 1985

O. G. D.  
ARTESIA OFFICEUNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
Artesia, NM 88210

## SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
See "APPLICATION FOR PERMIT—" for such proposals.OIL WELL ☐ GAS WELL ☐ OTHER ☐

WIW - TA

2. NAME OF OPERATOR YATES PETROLEUM CORP  
Newmont Oil Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 1305 Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

2310' FNL 2310' FWL Sec. 3-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

LC 058480

6. IF INDIAN, ALIOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

West Loco Hills Grb #4 SD U

8. FARM OR LEASE NAME

Tract 10A

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 3-18-29

12. COUNTY OR PARISH 13. STATE

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) P&A ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8/4/83/----Tagged bottom @ 2730'. Spotted 100 sacks cement w/2% calcium @ 2714'. WOC.

8/5/83-----Tagged plug at 2593'. Not enough plug. Mixed 2 sks paper and 2 sks cottonseed hulls followed by 100 sks cmt w/2% CalCl @ 2530'. WOC. Tagged plug at 2236'. Hole between 1000' and 1071'. Held at 300 psi. Perf. w/4 shots/ft. at 900'. Squeezed 50 sks cement at 598'. 500 psi. WOC.

8/6/83-----Plug held at 500 psi. Tagged plug at 750'. Perf. 4 shots/ft. at 390'. Squeezed 50 sks cmt w/2% calcium, SI - no pressure. WOC. Pressure to 500 ..Okay. Tagged plug at 273'. Mixed 15 sks cmt for top hole plug. Installed P&amp;A marker

Location cleaned, seeded and ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Edward J. McLaughlin*

TITLE

Area Manager

DATE

9/9/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

3-19-85

CONDITIONS OF APPROVAL, IF ANY: