

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

N.M. Oil Cons. Division  
811 S. 1st Street  
Artesia, NM 88210-2834

5. Lease Serial No.

061701

6. Indian Name or Tribe Name

N/A

7. If Unit or CA/Agreement, Name and/or No.

N/A

8. Well Name and No.

BALLARD B #3

9. API Well No.

30-015-03325

10. Field and Pool, or Exploratory Area

SEVEN RIVERS WILDCAT

11. County or Parish, State

EDDY NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- |   |   |   |   |
|---|---|---|---|
| <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume)      | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation                    | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                     | <input type="checkbox"/> Other          |
| <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input checked="" type="checkbox"/> Temporarily Abandon |   |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal                 |   |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

WELL WAS FORMERLY KNOWN AS THE BALLARD GRAYBURG SAN ANDRES UNIT #14-3.

1. INSTALL BOP. RLSE PKR.
2. SET CIBP @ 2810'. DUMP 10 SX CL "C" ON PLUG. WOC. TAG PLUG @ 2795'.
3. SET CIBP @ 2160'.
4. PERFORATE SEVEN RIVERS 2132-2142' W/4 SPF. FRAC W/50,795# SAND.
5. SWABBED & TESTED. FLOWED 100% WATER.
6. SET CIBP @ 2060'. DUMP 10 SX CL "C" ON PLUG.
7. PLUG BACK OPERATIONS UNSUCCESSFUL. WELL TEMPORARILY ABANDONED.

ACCEPTED FOR RECORD

Lara  
JUL 19 2001

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

SABRA WOODY

Title

ENGR TECH III

Date

06/26/01

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

RECEIVED

JUN 27 '01

WJ  
CONNELL, INC.