

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ALBUQUERQUE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUL 21 1983

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW - TA *PTA*

Name of Operator
Newmont oil Company ✓

Address of Operator
P.O. Box 1305 Artesia, New Mexico 88210

Location of Well
UNIT LETTER N 990 FEET FROM THE South LINE AND 1650 FEET FROM
THE West LINE, SECTION 10 TOWNSHIP 18 RANGE 29 N.M.P.M.

6a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-7677

7. Unit Agreement Name
West Loco Hills GRB # 4

8. Farm or Lease Name
Tract 42

9. Well No.
1

10. Field and Pool, or Wildcat
Loco Hills (O.G. SA)

12. County
Eddy

15. Elevation (Show whether DF, RT, GR, etc.)
3477'

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-16-83 75 sacks @ 2367'. Tag bottom @ 2382'.
3-17-83 Tag @ 2367'. 30 sacks @ 2367'.
3-18-83 Tag @ 2237'. Perforate @ 925'. Squeeze 50 sacks.
3-22-83 Pump 25 sacks @ 970'. 25 sacks @ 590'.
3-23-83 Perforate @ 340'. Could not pump into perf. Fill 7" casing with 66 sacks.
Braden head squeeze 26 sacks. Install marker.

*Post ID-2
7-20-83
RTA*

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Ernest J. McLaughlin* TITLE Area Manager DATE 7/20/83

APPROVED BY *Larry Brooks* TITLE *Geologist* DATE 10/7/83

CONDITIONS OF APPROVAL, IF ANY: