				- 15 1
RECEIVED BY	NITED STATES	TERIOR SUBMIT IN		Form approved. Budget Bureau No. 42-R1424. DESIGNATION AND BERIAL NO.
SEP 25 1985	GEOLOGICAL SURV	D π Ω π Ω Ω		LC-055374
SUN	ORY NOTICES AND REPORT orm for proposals to drill or to deepen o Use "APPLICATION FOR PERMIT_" for	RTS ON WELLS		IAN, ALLOTTEE OR TBIBE NAME
I. OIL GAS WELL	OTHER WIW - #	≠ <i>p</i> , <i>p</i> ,		GREEMENT NAME H.U. GRB #4 SD UT
2. NAME OF OFERATOR NEWMONT OIL COMPANY				or lease name ict 6
3. ADDRESS OF OPERATOR				NO.
P. O. BOX 1305, ARTESIA, NEW MEXICO 88210 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)				AND FOOL, OR WILDCAT
At surface				<u>Hills (Q. G. SA)</u> T., R., M., OR BLK. AND
660' FSL & 1980' FEL of Sec. 12-18-29				2C. 12-18-29 NMPM
14. PERMIT NO.	15. ELEVATIONS (Show wh 3522'	ether DF, RT, GR, etc.)	12. COUNT Eddy	TY OR PARISH 13. STATE J New Mexico
16.	Check Appropriate Box To Indi	rate Nature of Notice, R	eport, or Other Date	3
16. Check Appropriate Box To Indicate Nature of Notice, Report, or O				
		WATER SHUT-OF		REPAIRING WELL
TEST WATER SHUT-OF: Fracture treat	MULTIPLE COMPLETE	FRACTURE TREAT	-	ALTERING CABING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR A		ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	eport results of multiple	acompletion on Well
(Other)		Completio	n or Recompletion Repor	t and Log form.)
proposed work. If nent to this work.) *	COMPLETED OPERATIONS (Clearly state all j well is directionally drilled, give subsurfs	ice locations and measured and	tinent dates, including e 1 true vertical depths fo	estimated date of starting any r all markers and zones perti-
The above well wa	s plugged and abandon as	follows:		
12/15/82Well &	lowing back.			
12/16/82Set 7" perf b	cast iron bridge plug at ase of salt at 1045' and	2520'. Spotted 2 squeezed w/150 sac	25 sacks on plu 2ks cement, WO	g. Mudded hole up, C.
12/17/82Tagged 355'.	plug at 953', pressured Csg parted at shot, pump	up on csg to 800'r oed 120 sacks cemer	osi. Okay. Per it on back side	f top of salt @ . WOC.
12/18/82Tagged	plug at 40'. Set 15 sac	ek cement plug and	dry hole marke	r at surface.
Locati	on ready for inspection.			
				The summer process starting of the Start of Starting
			1 MAR 9 1	383 <u>20</u> 1
			OIL 8: 07	
18. I hereby certify that	the foregoing is true and correct	Acon Harmon	C C C C C C C C C C C C C C C C C C C	
SIGNED must	4. Horan TITL	E Area Manager		TE 5/8/83
(This space for Feder				re 9-2385
APPROVED BY CONDITIONS OF AP	TITL TITL	Е	DA?	11Bi)er

*See Instructions on Reverse Side