

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY(Other than for use on the
reverse side)

6. LEASE DESIGNATION AND SERIAL NO.

LC-060904

7. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OCT 11 12 51 AM '83

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

WIW - TA

BUREAU OF LAND MGMT
ROSWELL DISTRICT

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. BOX 1305, ARTESIA, NEW MEXICO

88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330 FNL 330 FEL Sec. 12-18-29

RECEIVED BY

NOV 28 1983

O. C. D.

ARTESIA OFFICE

10. FIELD AND POOL, OR WILDCAT

Loco Hills (O.G.Sa)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12-18-29

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3543'

12. COUNTY OR PARISH

Eddy

13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) P&A

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)7/13/83...Tagged bottom. Spotted 100 sks cement w/2% Calcium. WOC. Tagged plug at 2587'.
Pressured up to 500 psi at 820'. Held. Perf 4 shots/ft. @ 1170'. Squeezed 50 sks
cmt w/2% Calcium. SI 200 psi. WOC.7/14/83...Pressured to 500 psi. Held. Tagged plug at 1040'. Perf. 4 shots at 390'. Spotted
50 sks cmt w/2% Calcium. Bullhead squeezed w/200 psi. WOC. Tagged plug at 273'.
Pressure tested plug to 400 psi. Mixed 15 sks cmt for top hole plug. Installed P&A
marker.

Cleaned location, seeded and ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Area Manager

DATE 9/14/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: