

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other, instructi
here side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

LC-062029

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Brainard Tr. 2

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Turkey Track SR Q Grbg SA

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 34-T18S-R29E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

RECEIVED

2. NAME OF OPERATOR

Marbob Energy Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 217, Artesia, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2185 FSL 990 FWL

MAY 22 '89

C.C.B.
ARTESIA, OFFICE

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3416' GR

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and notes perti-
nent to this work.)

We propose to plug & abandon as follows:

Set a 100' plug @ 2085-1985' (tag); set 100' @ 1300-1200';
perf csg @ 965', 50' below base salt; try to circ cmt
to surface inside & outside 7" csg. If cannot circ,
sqz w/50 sx (tag); perf csg @ 275', 50' above top salt;
try to circ again or sqz w/50 sx 50' surface plug.
Install dry hole marker & clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Clerk

DATE

5/11/89

(This space for Federal or State office use)

APPROVED BY

FOR: TITLE

DATE

5/19/89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side