

November 1984
(Formerly 9-351)

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	NM OIL CONS. COMMISSION	5. LEASE DESIGNATION AND SERIAL NO.	NM - 01159
2. NAME OF OPERATOR	Drawer DE	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR	BelNorth Petroleum Corporation	7. UNIT AGREEMENT NAME	
3300 N. "A", Suite 201, Midland TX 79705	Artesia, NM 88210	8. FARM OR LEASE NAME	Nelson Fed
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)		9. WELL NO.	3
At surface		10. FIELD AND POOL, OR WILDCAT	Loco Hills (Queen, Grayb, SA)
2310' FNL & 1650' FWL		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	Sec 4, T-18-S, R-30-E
14. PERMIT NO.		12. COUNTY OR PARISH	Eddy
		13. STATE	NM

RECEIVED

JUL 13 '89

O. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREAT	☐	FRACURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)	☐

17. DESCRIBE PROPOSED OR COMPLETED WORK AT EACH STATE ALL PERTINENT DETAILS, AND GIVE PERTINENT DATES, INCLUDING ESTIMATED DATE OF STARTING AND PROPOSED WORK. IF NOT IS DIRECTLY DRILLED, GIVE SUBSURFACE LOCATIONS AND MEASURED AND TRUE VERTICAL DEPTHS FOR ALL MARKERS AND TONES PERTINENT TO THIS WORK.

5-23-85 RU Baber Well Serv rig, plugging equip & BOP. TOH w/108 jts 2-3/8", J-55, 8rd tbg. TIH w/tbg. Tag up @ 3487'. Circ hole w/10# salt gel. RU pmp truck & pmpd 50 sx cl "C" @ 3450'. WOC. RIH w/WL & tag @ 2315'. Perf 4 holes @ 1450'. TIH w/tbg to 1450'. Spot 35 sx cl "C" cmt. TOH. RU pmp truck & sqzd 100' outside & left 100' inside w/500 psi @ 2 BPM.

5-24-85 TIH w/tbg, tag plug @ 1362'. TOH. LD tbg. RIH w/WL & perf 5-1/2" csg w/4 shots @ 536'. RU pmp truck & pmp 135 sx cl "C" cmt. Circ backside & left 411' cmt inside csg. WOC. RIH w/WL & tag cmt @ 82'. Run 55 sx plug in top of csg. Cut off WH. Install dry-hole marker.

POST FD-2
6-21-85
P x A

I hereby certify that the foregoing is true and correct.

SIGNED: [Signature] TITLE: Senior Drilling Engineer DATE: 06-17-85

(This space for Federal or State office use)

APPROVED BY: _____ TITLE: _____ DATE: _____

CONDITIONS OF APPROVAL, IF ANY: _____

*See Instructions on Reverse Side

SJS