(Other)

ACTING DISTRICT ENGINEER

## INTERIOR (Other Instruction

SUBMIT IN TRIF

GEOLOGICAL SURVEY	LC 046256-A
SUNDRY NOTICES AND REPORTS C (Do not use this form for proposals to drill or to deepen or plug by Use "APPLICATION FOR PERMIT—" for such pro	ack to a different reservoir.
1. OIL GAS OTHER Plug and Abandon	T. UNIT AGREEMENT NAME
NEWMONT OIL COMPANY	8. FARM OR LEASE NAME Coppedge
3. ADDRESS OF OPERATOR P. O. BOX 1305, ARTESIA, NEW MEXICO	88210 ARTES C. (2) 9. WELL NO.
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with any S See also space 17 below.) At surface</li> </ol>	State requirements. QFF 10. FIELD AND POOL, OR WILDCAT LOCO Hills
330' FNL & 1980' FWL of Sec. 5; T-185;	R-30E  11. SEC., T., B., M., OR BLE. AND BURVEY OR AREA  Sec. 5-18S-30E NMPM
14. PERMIT NO. 15. ELEVATIONS (Show whether DF,	
16. Check Appropriate Box To Indicate No.	ature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON*  REPAIR WELL CHANGE PLANS	WATER SHUT-OFF  FRACTURE TREATMENT  SHOOTING OR ACIDIZING  ABANDONMENT*  XX

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was P&A as follows:

12-4-71: Set 7" cast iron plug at 2700' with 25 sks cmt.

and started pulling.

12-7-71: Pulled all of 7" csg, 1494'. Set 25 sks cement at 1500' and another

25 sacks at 465'.

Set pipe marker and 5 sacks cement and cleaned location.



18. I hereby certify that the toregoing is true and correct	TITLE Divn. Supt.	DATE 12/30/71
(This space for Federal or State office use)		
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE
DDKI!		

\*See Instructions on Reverse Side