OCD-Artesia

OSY

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NMLC049947A

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS! 10 31 All 33 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oil Well 8. Well Name and No. __ Other Yates #3 2. Name of Operator (505) 748-1471)9. API Well No. YATES PETROLEUM CORPORATION 30-015-04472 3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210 10. Field and Pool, or Exploratory Area Loco Hills Q-G-SA

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL & 1650' FWL of Section 6-T18S-R30E (SENW)

Loco Hills Q-G-SA

11. County or Parish, State

Eddy Co., NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water	
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon well as follows:

- 1. POOH w/tubing and packer. RIH w/bit & scraper on tubing and clean out to 2700'. POOH. Run cement bond log to determine top of cement.
- 2. GIH w/CIBP and set at 2655'. Dump 35' of cement on top of plug.
- 3. If top of cement is above the top of Queen (2300'±) spot a 25 sack cement plug from 2450-2150'. Tag plug.
- 4. If TOC is not above the top of the Queen, will perforate 4 holes at the top of the Queen. GIH w/cement retainer on 2-3/8" tubing and set 50' above perfs. Squeeze Queen with 50 sacks Class "C" 2% CaCl2. Dump 35' of cement on retainer. Pressure test casing to 500#.
- 5. If casing does not hold, RIH w/RBP and packer and locate holes. If holes are above the Base of the Salt (1130') and TOC is not above the base of the Salt, will perforate 4 holes at 1130'. GIH w/cement retainer and set at 1080'. Squeeze Base of Salt with 50 sacks Class "C" 2% CaCl2. Dump 35' of cement on retainer.
- 6. Perforate 4 holes at 440'.
- 7. GIH w/cement retainer on tubing and set retainer at 390'. Squeeze shoe/Top of Salt with 100 sacks Class "C" 2% CaCl2. Dump 35' of cement on retainer. CONTINUED:

14. I hereby cerylfy that the foregoing is true and correct		
Signed Kusty Klein	Title Production Supervisor	Date Sept. 15, 1993
(This space for Federal or State office use) Approved by (ORIG SGD.) IOF G. IAPA Conditions of approval, if any:	Title PETROLEUM ENGINEER	Date 10/12/93
		•

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NMLC049947A

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

orm for proposals to drill or to deepen or reentry to a different reservoir.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE I. Type of Well Oil Well Gas Well 8. Well Name and No. Other 2. Name of Operator Yates #3 (505) 748-1471)YATES PETROLEUM CORPORATION 9. API Well No. 3. Address and Telephone No. 30-015-04472 105 South 4th St., Artesia, NM 88210 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Loco Hills Q-G-SA 1650' FNL & 1650' FWL of Section 6-T18S-R30E (SENW) 11. County or Parish, State Eddy Co., NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* CONTINUED FROM PREVIOUS PAGE: If circulation is achieved, bring cement to surface in annulus and force outside 8-5/8" after cement is circulated. If cement is not circulated, perforate 4 holes at 60'. Attempt to establish circulation to surface through 7" X 8-5/8" annulus. Squeeze cement surface plug down 7" casing with returns through the 7" X 8-5/8" annulus. When cement is circulated, close annulus valve to force cement outside 8-5/8" casing. If cement was circulated outside casing, will set a surface plug from 60' to surface. Install regulation abandonment marker. NOTE: Mud will be placed between all plugs. NOTIFY NMOCD (748-1283) AND BLM (887-6544) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS. Sept. 15, 1993 Title Production Supervisor Approved by ______ Conditions of approval, if any: